AMERICAN MACHINIST

INDEX FOR VOLUME 31, 1908—Part ONE.

Explanatory Note.

Illustrated articles are marked with an asterisk (*). Book notices are marked with a dagger (†). Cross references to a particular initial word generally refer to any cognate work beginning in the same way. Thus, a reference from "Screw" to "Tap" would apply equally to "Taps," "Tapping," etc. The cross references are intended to condense the matter and assist the reader, but are not to be regarded as completely inclusive, exclusive or conclusive. So, if there were a reference from "Pattern" to "Foundry," and if the searcher failed to find the sought-for article under the latter entry, he should not regard it as useless to turn back and look through all the "Pattern" entries, or others that the topic may suggest, as he would have done had there been no cross reference.

A

PAGE

Accident congress, International. 882
Accounting, See also "Cost," etc.
Accounting, Burroughs plant.—Stock system; Balanced cost. A. J. Doughty. *792, *943
Accounting—G. E.'s pay-roll system, Lynn. *348
Accounting, Mare Is. H. A. Evans. *610, *645
Accuracy guarantees, Richards & Co.'s. *389
Accuracy in calculations, Limit of. N. P. Logue. 64
E. M. Senyour. 469
Acetylene gas and fire insurance. 363
Acetylene, Welding with. *515
Adding machine, Burroughs. *792, 796, 891, 943
Adding typewriter, Ellis, Making. *904
"Advertising Medium? What Makes the Best." E. P. Harris. †777
Advertising pages, The. J. R. Godfrey. 274
P. W. Abbott. 825
O. James. 957
A. Prince. 985
Air boiler-riveter installation, Albree. *56
Air chuck. Experimenter. *845
Air, Compressed, reaming bench, Chicago. *686
Air-compressing, Tidal, Rockland. W. O. Webber. *44
Air compressor, Portable, and pneumatic hammer. C. L. Hooker. *586
Air compressor, Variable-volume, Canadian Rand. H. V. Haight *679
Air-cooling table—Hardening cutters. *453
Air-compressor plant, Portable, Link-Belt. *923
Air, Dense, hoisting engine. 626
Air drill for close quarters, Chicago. *666
Air feeds, large Bement planer. *7
Air fixtures for holding work—Nat'l Cash Register Co.'s—Profiling, milling, etc. M. E. Service. *867
Air grooves in pulleys, Turning. ‡336
Air, High-pressure, joints and fittings for; compressors, locomotives, valves, packing, etc. Canadian Rand Co.'s and others. Haight and Batcheller. *633
F. W. O'Neil. *995
Air-hoist cylinders, Making. H. L. Burrhus. *321
Air system—Fuel oil, Mare I. *158
Alcohol, Tests with. Lucke, Woodward †143
Alcohol vs. gasolene—Govt. tests. 593
Alinement charts. J. B. Peddle. *757
Alining shaft bearings by wire. A. H. Nourse. *338
M. Preston. 770
Alley & Maclellan shop methods. *268
Alloy and other steels. E. F. Lake. *477
Aluminum, Cutters for. *690, *993
Aluminum in steel, E. F. Lake. 485
Aluminum, Lubricant for. C. G. H. 356
Aluminum castings, Burning in. 126
Aluminum, Dip for. J. Coapman. 766
Aluminum, Solder for. 781
Alzen. 351
Amalgams. 531
AMERICAN MACHINIST, Filing. W. C. McLeod. *726
AMERICAN MACHINIST, Writing for and reading. 250, 252, 589, 825, 957, 985
American Museum of Safety Devices. 298, 630, 891
American Sch. of Corr. pubs. †219
American S. M. E. See "Engineers."
Angle drive in small space. J. W. Greene. *398
Angle-heating furnace, Mare Is. *159
Angle plate, Drill-press. J. Dier. *849
Angles, Prof. Sweet's shop square. *929
Angles, Tool for laying out. W. T. Dillaway. *202
Annealing cutters. W. H. Booth. 605
Annealing, hardening, etc, tools. J. Steele. 673
Annealing high-speed steel. E. Viall. 315, 808
Annealing steel, E. F. Lake. *489, *490, 494
Apprentice training vs. machine-operator training. C. Alvord. 205
(Married men.) R. E. Marks. 280, 772
P. E. Tomb. 470
Entropy. 661
P. E. Noyes. 695
Apprentices. J. R. Godfrey. 255
Apprenticeship, Entropy. 60
E. Viall. 539
A. A. Priner. 694
Apprenticeship, Mach. Tool Builders and. 840
Apprenticeship—Natl. Soc. Idus. Ed., etc. 222, 256, 590, 693, 776, 806, 993
Apprenticeship—What next? J. G. Dornbirer. 597
A. B. Howk. *956
Entropy. 994
Arbor, Expansion. A. H. Gang. *930
Arbor, Fly-cutter. R. G. D. *657
Arbor for backing off cutters. *434
Arbor for slotting cutters. F. G. W. *911
Arbors, Expanding—Eccentric, etc. R. S. Brown. *393
H. Maplethorpe. *956
Arbors for profile cutters. M. E. Service. *867
Arbors, Standardizing; keys, etc. F. Oyen. *296, 774, 993
Arc lamp. See "Lamp."
Arc, Planing saddle pieces, etc, to. *216, *587, 773, *801
Arcs for drawing ellipses, Determining. *211
Area chart, Alinement. J. B. Peddle. *758
Armature-banding and field-coil winding lathe. Greaves, Klusman & Co.'s. *698
Armature punchings, Index die for. K. S. Allen. *946
Armature-segment punch and die. J. C. Haff. *910
Armor-plate shop, Creusot works. *862
Asbestos slates, Waterproof. 196
Assembling fixtures, Autoframe. C. A. Erickson. *350
Assistance, Unnecessary calls for, from machine purchasers. 809
Auger making in old shop. Pugh's. F. H. C. *281
Automatic vs. hand lathe. 346, *423, *469, 476, 527, 623, *917

AUTOMOBILE.

See also names of automobile-engine parts, etc.
—"Automobiles et leur Moteurs." de Chabot. †68
—Bearings, Mossberg roller, Data of. *239
—Brasses, Machining. *395, *1001
—Cadillac cylinders, Machining. E. F. L. *113
—Club's Wheeler dynamometer. E. F. L. *111
—Cooler fronts, Die for. *174
—Crank-shaft brasses, Machining. *395
—Cylinder machining, Alley & Maclellan's. *268
—Fly-wheels, Machining on Gisholt lathe. *167
—Frame-assembling fixtures. C. A. Erikson. *350
—Nut, Split, for assembling. F. H. McGee. *356
—Pressed-steel frames. E. J. Bartlett. *224
—Simplex autos., Building in N. Y. *599
—Variable-speed drive, Dieterich. *838
—Wrench, Monkey, Use in emergency. *61
Auto-truck, Ry., Westinghouse. *70

B

Babbitting mandrel. H. B. Robinson. *326
Babbitting rig, Auto. work. B. Sparks. *436
Back rests for box tools. *208, 468
Backing-off cutters in lathe. P. A. Fredericks. 951
Backing-off formed cutters in milling machine. J. E. Poorman. *629
Backing off formed milling cutters by hand. P. F. Setag. *434
Backing-off gage. S. Peters. *583
Backing-off taps and drills. *38
Baker compound planetary gear. *249
Balancing, High-speed. W. E. Snow. *8
(Simple rig.) R. Grant. *579
Balancing pulleys. Woods Machine Co.'s. ‡337
Balancing weights, Magnetized. M. B. H. *728
Ball. See also "Bearing," "Joint," "Chuck."
Ball-drilling jig. S. W. Green. *687
Ball-end work, Drilling. R. Grant. *468
Ball seats, Boring bar for. *658
Balls, Hollow, Press tools for. O. Clerk. *442
Bank, Manufacturers'—Wanted. 736
Banker's conveyer hooks. R. A. Gleason. *989
Bar. See "Boring," "Facing," "Tool."
Barium chloride for hardening. O. M. Becker. *519
Barrel-head rolling machine, Toledo. *448
Beam design, Notes. G. E. Flanagan. *286
Beam flanges, Triangle for drawing. *64
Beams, Circular. Con Wise. *905
Bearing, Ball, on Potter graining machine. *310
Bearing, Ball, universal joint, Kinsler-Bennett. *258
Bearing, Cam-adjusted, Challenge. *924
Bearing, Rifling, for oil. W. A. M. *948
Bearing surfaces, English lathes. *105, *173, 287, *466, *530, *576, 734
Bearing surfaces, Scraped. H. L. Cameron. 249
D. C. Howard. 291
Bearings, Alining. *338, 770
Bearings, Ball, Factor of safety in; new spherical roller and several designs. G. T. Rennerfelt. *720, 817
Bearings, Ball, High-speed. J. Broadbent. *907
Bearings, Ball, Manufacture and tests of Chapman double. *129
Bearings, Ball-shaped and other, caps, etc., for steel-mill machinery—Milling cutters at Kneeland shops. *894
Bearings, Bogert's lapping machine for. *786
Bearings, Gas-engine. C. Kaufmann. 323
Bearings in place, Casting bronze. *621
Bearings—Limit of proportionality and elastic limit. H. Hess. *397
Bearings—Making auto. brasses. *395, *1001
Bearings, Roller, Proportions and loads—Mossberg thrust, auto., etc. *238
Bearings—Stribeck's Sellers; Heimann's; allowable pressure; fast-collar and forced lubrication—Friction and lubrication. J. T. Nicholson. *46, *80
Bearings of large Bement planer. *5
Bed, Inverted-V vs. flat. F. J. B. *105
John E. Sweet. *173
J. P. Wheeler. 287
Entropy. *466
F. Pike. *536
R. Thompson, J. Vose, E. A. Dixie. *576
A. I. Dodge. 734
Bell, Electric, for machines. A. D. Allen. 140
Belt horse-power chart. J. J. Densman. *972
Bell housings, Boring bar for. *846
Belt coupling, Flexible metallic, Tostevin & Cottle. *699

PAGE
Belt pole. D. H. Smith. *216
Belt shifter. C. Bentall. *986
Belt shifter, German. F. C. Perkins. *981
Belt shifter, Novel. J. T. Allen. *214
Belt tightener, Allen drill press. *72
Belt tightener, Motor-countershaft, Crocker-Wheeler. *331
Belt tire drive for turning wheel journals. H. W. Jacobs. *418
Belts, Emery-cloth, Blevney's use of. *419
Belts, Power losses in high-speed. A. S. Dickinson. 555
Belting grinder wrongly. J. N. Heald. *560, 809
Belting, Steel. 978
Bench centers. Entropy. 324
J. E. Sweet. 578
Bench centers, Wells. *544
Bench-lathe schemes. F. J. LeCard. *244
Benches, Pattern-shop. Md. Steel Co.'s. *202
Benches, Work, Four styles of. *352
Bending clutch fingers. F. H. C. *574
Bending sheet metals. C. F. Howse. *579
Bessemer process. E. F. Lake. *477
Blacksmith shop, Oil fuel, Mare Is. *154
"Blacksmith's Guide." J. F. Sallows. †31
Blast-furnace casting. W. H. Booth. 253
Blocks, Planer-leveling. *535, *670
Block gages, Sets of. *403, 914
Blocks, Size; leveling block—Bullard. *713
Blocks, Stepped, at Lucas shop. *978
Blocking, Adjustable, for Bullard boring mill. Wm. Casey. *729
Blowers, Foundry, Motor-driven, Root. *855
Blowers, Sturtevant turbine cupola. *541
Blue-print room, Compact. A. B. Howk. *896
Blue-print washers and driers; tracing blue-prints. Md. Steel Co.'s. *202
Blue-print drying machine, Toerring. *853
Blue-print substitute—"Raven" method. 962
Blue-printing apparatus, Gould & Eberhardt's. *376
Blue-printing machine, Duplex, "Tec." *666
Bluing tool handles. F. Webster. 985
Boiler-riveter installations, Albree. *56
Boiler-sheet flanging press. W. J. Withem. *682
Boilers, Cutting holes in—Tools. *88, *89
Boilers, Oil-fired, Mare Island. *153
Boilers, Steel used in. W. H. Booth. 408
Bolt cutter, Stay. Landis. *146
Bolts with rolled threads, Size of stock for. S. A. Gorman. 177
Bolted down? Why is planer. 137, 250, 325, 355, 403, 437, 445, *535, 662, *670
Books, Technical Inaccuracies. P. R. Hough. 476

BORING.

—Bar, Boring, Fine adjustment of; vernier. M. M. Sharp. *434
—Bar, Boring, for bell housings. *846
—Bar, Boring, for spherical seats. A. Newman. *658
—Bar—Counterboring opposite side of hole. *692
—Bar cutters, Round boring. J. R. Godfrey. *527
—Bar for heavy work. W. George. *987
—Bar for loco. rocker arms. *86
—Bar, Handy boring. T. Dewitt. *216
—Bars, Boring, for turbine casings; feeding driving headstock itself, etc. T. M. Lowthian. *464
—Boring and turning mill, Duplex turret-head; spring counterbalance. Richards & Co., Ltd.'s. *391
—Boring machine, Horizontal, Patterson. *779
—Boring machine, Lucas, Building. *974
—Boring mill, Bullard vertical, tools and accessories—Combination boring and reaming bar; cutter grinder; size blocks; leveling block; square tester; cutting tools; O. K. combination tool holder; tool stand, etc. *713
—Boring-mill, Bullard — Adjustable blocking. Wm. Casey. *729
—Boring-mill chip guard. E. A. Dixie. *952
—Boring mill, Motor-driven car-wheel, with automatic chuck, Sellers. *741
—Boring-mill rig for large fly-wheel. P. Fenaux. *953
—Boring-mill uprights set with level. *669
—Boring mills, Niles—Thread cutting; fly-wheel and locomotive work; taper attachments. *412
—Boring mill work—Fuse bushings. *37
—Boring, reaming and tapping machine, Baker. *698
—Connecting-rod brasses, Boring and turning fixtures for. E. Beck. *769
—Counterbore—Drifting holes. J. A. Early. *291
—Counterbore for centers. R. S. *773
—Counterbore for porcelain, Bench-lathe. *244
—Counterbore, Improvised. A. B. Taylor. *246
J. P. Wheeler. 400
—Counterboring and facing tool. M. R. Kavanagh. *913
—Counterboring textile rolls. *26
—Cylinder boring, Auto. H. Munro. *271
—Cylinder-boring cutter. L. A. P. *65
—Cylinders, Bardons & Oliver tools for auto. *531
—Cylinders, Boring small curved. *346
—Cylinders, Gas-engine. W. Osborne. *194
—Cylinders, Boring Cadillac—Duplex machine. *113
—Drilling, boring and milling machine, Hamilton. *474
—Eccentric chuck for tool. Jared. *848
—Heads, Boring, Stopping chatter on large. J. Green. *175
W. J. Chambers. *535
—Indexing job. E. W. Richmond. *354
C. H. Erb. *880
—Jigs, Boring, without laying out, etc. *321, *358, 402, 403, *433, *623, 796
—Master-plate work. G. H. Bert. *588
—Motor frame, Car, Boring machine, heads and jigs for. *384
—Nozzle, Boring special. F. E. Fick. *768
—Piston rings, Jig for. W. J. B. *948
—Portable machine on planer bed. *5
—Reamers for choke boring guns. *614
—Simplex autos., Making—Boring crank case; tool drives, etc. *600
—Spindle-boring drill, Oesterlein. *743
—Spindle-boring lathe, LeBlond double-ended. W. F. Groene. *707
—Tool, Adjustable turret-lathe. J. E. Ritchie. *213
—Tool, Boring, Adjustable, for turret lathe. W. Alton. *581
—Tool, Boring, Evolution of. W. Osborne. *899
—Tool, Boring, Expanding. J. Wheeler. *438
—Tool, Boring, Readily removable. H. H. G. *949
—Tool, Combined boring and threading. P. A. Frederick. *175
—Toolholder, Boring, Mayer's. *553
—Wheels, Car, Boring and facing. B. W. T. *394
Bower-Barff finish, Producing. 765
Box, Hanger, for grease or oil. *738
Box, Press tools for small tin. W. Sirius. *288
Box tool, Special. W. T. H. *911
Box tools. Goodrich & Stanley. *207
Bracket, Machining. H. C. Barnes. *672
Bracket, Reel. B. C. Hay. *803
Brackets, Machining turret-tool. *20
Brake, Band, proportions, Chart for. *754
Brake shoe, Red fiber. E. D. Gagnier. 879
Brakes for hoisting engines. H. L. Bunhus. 779
Wm. Whaley. 954
Brasses, Auto. crank-shaft, Machining. R. Rotom. *395
Brasses, Engine, Making. R. Whaley. *1001
Brazing cast iron. F. L. Nichols. 64
Broach, Surfacing, for Bullard wrench. *463
Broach, Washer, Adjustable. E. Viall. *691
Broaches for Monotype making. *788
Broaching—Drifting holes. J. A. Early. *291
Broaching job, Delicate—Slotted brass plugs. K. E. Lemer. *538
Broaching machine, Hand. A. C. Pletz. *598
Brushes, Drilling back for. G. H. Smith. *289
Buffers, Car, Lorenz, lathe for. *791
Buffing lathe, Webster & Perks. *186
Business rivals. (Poetry.) Mekeel. 409
Burner, Oil. See "Oil."
Burning new flange on double cylinder. *425
Burroughs Adding Mach. Co.'s stock system. *792
—Precision drilling and reaming. 796
—Reclaiming gasolene. 891
—Balanced cost accounting. 943
Bushings, Fuse, tools and output. *37
Bushings, Locating—Nice indexing job. *354, *880
Bushings, Movable—Table of proportions, etc. A. J. Baker. *101
M. R. Kavanagh. *175
(Sliding, etc.) P. Princeps. *287
L. Haas. 443
C. I. Innis. *471
E. A. Dixie. *735
Bushings, Standard cast-iron. *373
Bushings, Toolholder clamp, Fixtures for turning and facing. E. I. Phipps. *440
Business depression, The. 256, 295, 470, 587

C

Cabinet, Drawing-paper. Md. Steel Co.'s. *204
Cadillac cylinders, Machining. *113
Calculations, Accuracy limit. N. P. Logue. 64
E. M. Senyour. 469
Caliper. See also "Micrometer," "Vernier," "Gage," "Indicator," "Dividers."
Caliper rest, Inside. W. Gribben. *470
Calipering, Accurate. W. S. Romell. 239
Cam adjusting, Cleveland screw machine. *275
Cam cutter, Manville Bros.' *906
Cam-cutting machine, E. J. Manville Machine Co.'s automatic. *182
Cam grinder, Schuchardt & Schütte's. *963
Cam-grinding rig, Premier auto. *712
Cam levers for small tools. P. S. Sehwim. *27
Cam shaft of Simplex auto., Milling. *602
Cams, Friction of. Con T. Wise. *196
Cams, Master, Methods of making—Milling machine work; blackened zinc templet. W. V. Lowe. *308
J. Coapman. 584
Cams, Screw-machine, Cleveland machine for milling. J. P. Brophy. *902
Camera for photos. without negative. *781
Cans—Solder cap hemming machine. *778
Canada, Labor conditions. B. Barcroft. 166
H. L. Meyer. 403
Cap, Dust—Facing and threading. *727
Cap, Dust—Machining. B. J. Williams. *971
Caps for projectiles, Making soft. *39
Caps, Index drilling of. G. Huber. *467
Car wheel. See "Wheel."
Carbonizing steel. E. F. Lake. *263, *497
Carborundum tool, Turning hard lathe center with. H. F. J. 173
Card system, Burroughs Adding Mach. Co.'s. *792
Cards; holders on lathe, Mare Is. *648
Cartridge cases, Turret for, Bardons & Oliver. *945
Case-hardening, New applications. P. C. Osterman. 237
Case-hardening steel with gas, etc. E. F. Lake. *263, *497
Casting. See also "Foundry," "Blast-furnace."
Casting bronze bearings and valve seats. *621
Casting—Varying from blue-print—Law. 41, 620
Castings, Die, Producing. E. L. Lake. *227
Castings—inspection system neglected. 812
Cat heads for loco. work, connecting rods, etc. L. E. Salmon. *86, *461
Catalogs, Pays to send. E. A. Riell. 245
Cement for iron on marble. 533
Center, Ball-bearing revolving lathe. *391
Center blocks for crankshafts. *834, *835
Center, Facing work up to. R. D. Morse. *732
(Counterbore.) R. S. *773
Center grinder, Electric, U. S. *697
Center, Turning hard lathe, with carborundum tool. H. F. J. 173
Center, V. drilling. W. I. Jehn. *661, 954
Centers, Bench. Entropy. 324
J. E. Sweet. 578
Centers, Bench, Wells. *544
Centers, Dividing-head, Tests of. *12
Centers, Keying lathe. F. Oyen. *296
Centering brass cock keys. E. Viall. *247
Centering to mill motor-cover seat. *385
Chain belt and adjustable pulley, Whitney. *778
Chain countershaft drives—Renold works. *416
Chain-repair block, Diamond. *699
Chain-stud recessing machine, Renold. *16
Chain—Way to use link-belt. *748
Chain, Welding. H. Barnes. *949
Chalking, Liquid, for sheet-metal work. H. L. Burrhus. *321
Chambering holes, Tools for. *103, *733
Chamfering attachment, "Long-Arm" tooth. *331
Chart, Belt horse-power. J. J. Densman. *972
Chart for shaft sizes. J. H. Barr. *900
Chart, Hoisting-hook. A. Pederson. *170, 181, 587
Charts, Graphical, Construction. J. B. Peddle. *753
Charts, Simple, from complex equations. 181
Chasers, Circular thread. M. A. Young. 588
Chasers, Die, Hobbing. E. A. Dixie. *653
Chasers, Making inserted. Goodrich and Stanley. *380
Chatter on large boring heads, Stopping. J. Green. *175
W. J. Chambers. *535
Check systems, Toolroom. *252, *336
Checking drawings. K. S. Allen. 59
T. H. Hanley. 361
Gould & Eberhardt's. *373
G. F. Howse. 442
Checking system, Toolroom. W. H. Taylor. *123
"Chemistry, Engine-Room." A. H. Gill. †473
Cherry stone, Spoons in. *59
Child labor—Natl. Asso. of Mfrs. 842, 844
Chile, Shop work in. A. Prince. 817
Chilean market for tools. A. Prince. 908
Chill, New car-wheel. *425
Chip guard, Boring-mill. E. A. Dixie. *952
Chips, Emery-wheel. C. H. Norton. *452
H. A. Richmond. *771
H. F. Noyes. 807
Chips from steel rolls. E. F. L. *893
Chips, Long curly, Breaking up. W. Gribben. *536
Chips, Oil evaporator for. *889
Chromium steels. E. F. Lake. 484, 496, 498, *505, 512, 514
Chuck, Ball. C. T. Keefer. *438
Chuck, Cheap magnetic. E. J. Williams. *583
Chuck, Drill, Geared, Skinner. *699
Chuck, Drill, Key wrench. B. M. Weller. *729
Chuck, Eccentric, for boring tool. Jared. *848
Chuck for ball-bearing housings. *132
Chuck for centering cock keys. *247
Chuck for dust cap. B. J. Williams. *971
Chuck for holding pulleys, Rockford. *629

PAGE

Chuck for nurling. E. A. Dixie. *65
Chuck for screw-cutting attachment. *100
Chuck-jaw faces, Milling three. *176
Chuck, Planer. A. E. Robinson. *941
Chuck, Pneumatic, for screw machine. Experimenter. *845
Chuck, Screw-machine, Auto. P. O. Dodder. *435
Chuck, Special 2-jawed, for metal core-box work. Viall and Voelcker. *762
Chucks, Bench-lathe. F. J. LeCard. *244
Chucks, Draw-in, Engine-lathe. E. A. Dixie. *913
Chucks, High-speed drill, Whitman & Barnes. *543
Chucking bevel-gear blank. F. E. Brown. *709
Chucking-machine drill support. A. M. Peck. *445
Chucking, Parallels for. C. E. Tanner. *727
Chucking thin work. C. Sherwood. *177
Chucking warped gears. Ste' A. A. E. P. L. *615
Cincinnati, Courses at Univ. of. 180, 555, 710, 290, 407, 841, 920
Cincinnati Shaper Co.'s tools and methods. *935
Cincinnati, The lesson of. 472
Circle—Circumferential distance table. J. Fraser. 767
Circle diameter and area, Scales of. *753
Circular beams. Con Wise. *905
Circumferential distances, Table of divisions corresponding to. J. Fraser. 767
Clamp, Toggle. A. E. R. *176
Clamp for holding screws. F. P. *214
Cleaning work for electro-plating. 609
Clearance, Side, circular tools. McK. *775
Clearances, Forming-tool. Goodrich, Stanley. *299
Clearing up old plant. B. H. Spencer. 367
Clock-pinion jig; micrometer head. *692
Clock, Shop, etc. Dornbirer, Entropy et al. 597, 956, 994
Clock with 40-ft. dial. Colgate & Co.'s. *783
Clocks—Beat tool for escapements; micrometer nuts for pendulums. W. Gribben. *439
Clutch, Cone, Repairing; inserting wooden plugs. S. P. Yeo. *246
Clutch fingers, Bending. F. H. C. *574
Clutch, Friction, Akron. *884
Clutch, Friction, without toggles, Hilliard. *961
Clutch gears, Cutting on press. *601
Clutches—Reversing devices. L. D. Burlingame. *189, *234
Coal burning, Smokeless, Illinois. 142
Coal, Weathering. Parr and Hamilton. †363
Cock keys, Centering brass. E. Viall. *247
Cocks, Metal core boxes for. *762
Coins, Making dies for Canadian. W. L. McLaren. *530
Collar, clamp, dimensions—Hollow mills. *209
Collars, Drilling and tapping in lathe. G. Allen. *443
Collection end of machine business. I. C. Koehne. 90
Comparator, Bench, Lanston Co.'s. *120
Compressed air. See "Air."
"Concrete, Tests of." A. N. Talbot. †997
Condenser tubes, Tool for packing. *240
Cone, Turning parabolic. W. Gribben. *260
Connecting-rod brasses, Boring and turning fixture for. E. Beck. *769
Connecting-rods, Cat heads for. L. E. Salmon. *461, *88
Connecting-rods—Making Simplex autos. *604
Contracts with dealers and customers, Uniform. 840
Conveyer hooks, Making. R. A. Gleason. *989
Conveyer, Small-tool. P. G. Roberts. *24
Cooling in heat treatment of steel. 488
Cooling table, Air—Cutter hardening. *453
Co-operation versus duty. 473
Copper casting, Silicium in. 947
Copper in steel. E. F. Lake. 482
Copper-plating, Simple. 255
Core-box; Difficult metal—Special tools. E. Viall and J. J. Voelcker. *762
Core boxes, Making by Fox machine. *982
Core boxes, Using sheet metal for. J. L. Gard. *803
Core oven, Oil-fired, Mare Is. *161
Cores, core sand and core-making machinery. G. H. Wadsworth. 74
Cores, Wax tapers for. J. B. Sperry. 849
Corner shields. Entropy. *620
Corrugating copper rings for superheaters, Die for. G. A. Beaudry. *322
Cost. See also "Accounting."
Cost accounting, Drafting. G. H. Haigh. 949
Cost accounting under reduced output. (Actual and standard.) H. Emerson. 470
W. Sangster. 587
Cost accounting, Uniform—Mach. Tool Builders. 840, 958
Cost cards, Gould & Eberhardt's. *376
Cost—Expense analysis. 106
Cost reduction on job. F. E. Brown. *709
Costs—Different methods. S. Laurence. *654
Counterbalance, Spring, Richards boring mill. *392
Counterbore. See "Boring."
Countershaft drives, Chain—Renold works. *416

PAGE

Countersink, Adjustable. E. Viall. *353
Countersinking tools for nut backs. J. V. H., T. Atherton, M. E. Chase. *292, *324, *915
Counting and weighing machine, National. *817
Coupling, Flexible insulated, Nuttall. *815
Coupling, Grisson flexible. *407
Coupling, Shaft, Oval. *148
Couplings for high-pressure air. *633, *995
Crane, Jib, at Lucas shop. *976
Crane lifting-magnets. F. C. Perkins. *528
Crane-power chart. A. D. Harrison. *964
Cranes, Overload detector for, Weston. *960
Crank-grinding machine. E. A. Shriver. *725
Crank-pin turning device. T. Evans. *285
Crank-shaft. See also "Shaft."
Crank-shaft and case—Making Simplex auto. *600
Crank-shaft brasses, Auto., Machining. R. Rotom. *395
R. Whaley. *1001
Crank-shaft, Saving a. R. D. Redins. *730
Crank-shaft work—Bogert's lapping machine. *787
Crank-shafts, Multiple-throw, Holder for hardening. R. B. B. Little. *962
Crank-shafts, Multiple-throw, Machining—Milling, turning, grinding. J. C. Spence. *833
Creusot works. J. B. Van Brussel. *857
Cup, Joint, removed by steam. *880
Cupola demonstration, Bailot Co.'s. 812
Curves, Spiral, Instrument for. *809
Curved faces, Planing. See "Planing."
Cutter. See also "Milling," "Gear," "Tool," "Grinding," etc.
Cutter, Circular forming, problem—60-deg. points on wire. I. G. Owen. W. Gribben, W. S. Barnes, S. Faris, B. S. Frank. McK. *443 *810 *880
Cutter, Cylinder-boring. L. A. P. *65
Cutter, Double facing. C. P. H. *689
Cutter, Fly-, arbor. R. G. D. *657
Cutter for nurl, Finding angle of. *435
Cutter, Gear, test. N. B. Chace. *936
Cutter, Hardening. E. R. Markham. *63
Jas. Steele. *619
(Nut-forming tool.) E. Viall. *955
Cutter head, Boring-bar. W. Osborne. *195
Cutter, Inserted-tooth fan-milling. A. York. *396
Cutter, Milling, Large-radius, and its grinding fixture. C. E. Chamberlain. *879
Cutter, Milling, Profile-steel. F. J. Bostock. *916
Cutter, Panelling, Grinding. *88
Cutter teeth, Form. B. S. Frank. *29
Cutters, Boring-bar, Bullard grinder for. *713
Cutters, Box-tool. Goodrich & Stanley. *207
Cutters, Churchill lathe for relieving. *389
Cutters, Expanding, for Cadillac cylinders. *114
Cutters for metal core boxes. *762
Cutters for milling ball-shaped and other bearings at Kneeland shops. *894
Cutters, Formed, Backing off. *434, *583, *629, 951
Cutters, High-speed steel formed milling—Hardening; forming teeth; grinding. H. T. Ashton. (Mfr. and up-keep—Annealing; finishing.) W. H. Booth. *453 605
Cutters, Inserted-tooth, for milling aluminum. S. Lawrence. F. Radford. *690 *993
Cutters, Inserted-tooth. M. R. Kavanagh. 471
Cutters, Lubricating. J. R. Godfrey. 274, 622, 674, 914
Cutters, Milling, High-speed steel, Recutting on grinder. W. Alton. *839
Cutters, Milling, Number of teeth in. J. Butterworth. *616
Cutters, Round boring-bar. J. R. Godfrey. *527
Cutters, T-slot. *22
Cutters, Using beveled side of wheel in grinding. 248, 401, 431, 537, 775
Cutting-off machine, Newton. *447
Cutting-off-machine speed control, Hurlburt-Rogers. *553
Cutting-off machine with inserted-toothed blade, Gorton. *365
Cutting-off tool for large guns. *104
Cutting with oxy-hydrogen. 320
Cyanide, Need of care with. S. A. Nyde. 457
Cyclometer, Making the Veeder. F. H. C. *797
Cylinder-boring cutter. L. A. P. *65
Cylinder, Double motor, Burning on new flange. D. Whyte. *425
Cylinder flanges, Turning hydraulic. L. F. Charles. *357
Cylinders, Gas-engine—Rotary-planer work. *980
Cylinder, Hydraulic, Molding. D. S. Fides. *818
Cylinders, Auto, boring and facing—Bardons & Oliver tools. *531
Cylinders, Auto., Thompson attachment for grinding. *421
Cylinders, Expanding tool for machining. *529
Cylinders, Machining Cadillac gaso. engine. E. F. L. *113
Cylinders, Machining small curved. F. J. Bostock. *346
Cylinders, Machining, by Alley & Maclellan, Glasgow. H. Munro. *268
Cylinders, Machining Reid Co.'s Oil Country. W. Osborne. *194
Cylinders, Making air-hoist—Wearing pipe smooth. H. L. Burrhus. *321
Cylinders of Simplex autos., Making. *599

D

Damage reports. H. A. Evans. *610
Davis, C. T., Death of. 892
Decimal equivalents, Scale with. A. E. C. 690
Defects, Claims for. 841
Derrer universal shape attachment. *147
Design. See also "Machine," "Drawing."
Design, Machine-tool, in engineering course. E. H. Fish. *932
Design of 36x36-in. planer. Entropy. *873
Designer with DT's. G. W. Koretke. 289
Designer's trouble, Tool. A. J. Baker. 253
W. C. Hartly. 285
Details often overlooked. R. D. Morse. *732
Diagram. See also "Chart."
Diagram construction. J. B. Peddle. *753
Diameters, Forming-tool, Finding actual. *300
Die castings, Producing. E. L. Lake. *227
Die, Press. See also "Press."
Die, Drop-hammer, made of poor steel —Hardening. K. Chambers. 584
Die stock, Pipe, Hart. *547
Dies and taps for automatic screw machines—spring and button; releasing die holder, etc. Goodrich and Stanley. *379
Dies, Hardening. C. R. Claver. 127, 661
Dies, Wire-drawing—McFarland foundry. *718
Dies, Wrench, Simple. T. Toot. *847
Different ways, same jobs. S. Laurence. *654
Disks, Manganese-steel, for lifting magnets, Cutler-Hammer. 888
Dip for aluminum. J. Coapman. 766
Dividers, Setting accurately. G. A. Doppmann. 849
Dividing between holes, Sector for. *103
Dividing-head tests, Cincinnati hobbing machine and. *10
Dovetail forming tools, Making. *302
Dovetail slides, gibs and V's, Measuring. F. H. Scheu. *650
Dowel holes, Roberts jig for. *855
Draftsman. See "Drawing."
Draw-in attachment. Adjustable collet Co.'s. *187
Drawers, Clearing shop. J. R. Godfrey. *527
DRAWING.
—See also "Blue-print."
—Board for detail work, with reference back. R. G. Pilkington. *616
—Checking drawings. K. S. Allen. (Criticism before detail.) T. H. Hanley. 59 361
C. F. Howse. 442
—Cost-accounting method. G. H. Haigh. 949
—Drafting machine, Universal, Using on vertical drawing board. J. A. Chappins. *584
—*Drafting*—New periodical. †295
—Drafting room, Complete and simple —Gould & Eberhardt's—Routine, blackboard, standards, cast-iron bushings, ground-fit limits, dimensions, alterations, checking, material order lists, numbering, index form, work tag, work and cost cards, records, blue-printing apparatus. W. F. Zimmermann. *371
—Drafting, Short-cut in—No pencil-ing, etc. W. R. Humelbaugh. 136
—Draftsman, Status of. W. C. Hartly. 285
—Drawing room, Maryland Steel Co.'s —Blue-print washers and driers; drawing on tracing paper; tracing blue-prints; sketch books; cabinet; paper and cloth cutter. H. J. Kennedy. *198
—Drawings, 6x10-ft., Making. H. F. Noyes. *430
—Eraser, Motor-driven, Coates. *961
—Ink, Higgins', Eraser for. 659
—Kink, Tabulation. J. C. Austin. 471
—Kinks—Triangle battered for drawing flanges, etc.; pencils connected for parallel lines. A. L. Campbell. (Parallel ruler.) Iron Burgh. *64 *917
—Library, General. W. J. Bitterlich. 378
—Machine-tool design, Worcester Polytechnic. E. H. Fish. *932
—"Mechanical Drawing." E. Kenison. †219
—Operation sheets, Alley & Maclellan's. *268
—Personal factors of safety. W. Osborne. 128
—Prints, Duplicating, "Raven" system. 962
—Protractor, Draftsman's, Kelsey's. *667
—Short cuts; tracing; detailing. C. J. F. 433
—Templets for milling-machine platens. S. W. Mills. *175
—Toolmaking without drawings. 749, 919, 957
—Tracing drawings—Details. W. J. Chipman. 245
—Tracings, Straightening. 580, 663, *770
—Triangle, Graduated. A. H. Stork. 727
Drift and hammer, Drill-press. J. B.

PAGE

Sperry. *687
Drifting holes. J. A. Early. *291
DRILL.
—See also "Jig," "Chuck," etc.
—Air drill for close quarters, Chicago. *666
—Automatic drilling machine, Fay. *341
—Ball ends, Drilling. R. Grant. *468
—Balls, Drilling. S. W. Green. 687
—Broken drills, etc., Removing. J. E. P. 355, *177, *585, *880
—Broken-shanked, Repairing, G. Roy. *61
—Bushings, Drilling fuse, Watervliet. *37
—Check system, Toolroom. R. Charlton. *252
—Chuck, New-model geared, Skinner. *699
—Collars, Drilling in lathe. G. Allen. *443
—Cross-drilling attachment for National-Acme screw machine. J. Acton. *628
—Cross-drilling tool, Landa's. *406
—Cylinders, Machining Alley & Maclellan auto.—jigs, 12-spindle flange drill, etc. *272, *274
—Deep-drilling lathe, LeBlond. *707
—Deep-drilling machine, Vertical, Oesterlein. *743
—Dowel holes, For—Roberts jig. *855
—Drift with hammer. J. B. Sperry. *687
—Drill jig for cotter-key hole in bolt; jig for oil hole and shield on 2-spindle press. F. Sellit. *734
—Drill press, All-geared. Barnes Drill Co.'s. *699
—Drill-press, Allen high-speed ball-bearing, with belt tightener. *72
—Drill press, Combination, Lapointe. *740
—Drill-press combination, Peculiar. Cincinnati M. T. Co.'s, made for Shanks & Co. *552, 592
—Drill-press job—Machining dust cap. B. J. Williams. *971
—Drill-press specialist. W. Osborne. 23
—Drill press, 12-inch, Ramsey. *183
—Drills and chucks, High-speed, Whitman & Barnes. *543
—Drilling and milling machines, Knight, Work of. *722
—Drilling, boring and milling machine, Hamilton. *474
—Drilling closely-spaced holes—Brushes. G. H. Smith. *289
—Drilling fixture, Turret-lathe. Egypt. *435
—Drilling holes crosswise through round rods. W. Gribben. *25, 954
(V center.) W. I. Jehn. *661
John E. Sweet. 733
—Drilling machine, Multiple-head, National. *705
—Drilling machine, Multi-spindle, Sargent. *332
—Drive, Drill, Double-tang, Cleveland. *702, 779
—Expanding tool. C. B. Kirkham. *529
—Extensions. G. M. Diehl. 735
—Fixture for holding rods while drilling—Angle plate. J. Dier. *849
—Grinder, Drill and cutter, Wilmarth & Morman. *890
—Grinding jig—Centering cock keys. *247
—High-duty drill, Foot-Burt. *546
—Index drilling of caps. G. Huber. *467
—Index-plate drilling machines, LeBlond and Hendey. *750
—Knockout fixture, Socket. H. T. Green. *659
—Lathe, Engine, Drilling in. C. E. P. *394
—Loco.-frame drill, 4-spindle, Harrington, for Am. Loco. Wks. *886
—Magnet-frame drilling machine. P. Fenaux. *832
—Motor frame, Car, Machining. P. Fenaux. *384
—Multi-spindle drill, Adjustable, Gardham. *739
—Multiple drill head, Bocorselski's. *922
—Oval taper—Derrer lathe attachment. *148
—Portable drill press, Kneeland shops. *896
—Portable-drill work, building planer. *6
—Portable electric drill, U. S. *553
—Portable electric drill, Hisey-Wolf large. *34
—Portable German and English drills on trucks. F. C. Perkins. *54
—Precision drilling and reaming machines and drills; Burroughs practice, etc. H. P. McCabe. *623
J. G. Vincent. 796
—Profile steel, "New Metal." *220
—Radial drill, large universal. Niles-Bement-Pond Co.'s. *814
—Radial drill, large, 2-spindle, Hessenmuller. 925
—Radial-drill speed box, Gang Co.'s. *854
—Ratchet drill, Short-head, Armstrong. *888
—Ratchet work, Machine for saving hand, at Woods shop. *337
—Sensitive and radial drill, Archdale. *390
—Sensitive drill, Friction-driven. Fleming Co.'s. *814
—Sensitive drill press, Washburn Shops'. *549
—Sensitive, Motor-driven Washburn Shops'. *697
—Sensitive, with hand-lever feed. W. F. & John Barnes Co.'s. *331

PAGE

—Simplex autos, Making—Universal *60
—Sensitive, Turret attachment for. R. Brown.
drill and jig for water-jacket covers; drilling crank case; threading on drill press; tool drives, etc. *559
—Spindle, Extensible drill. C. A. Edwards. *324
—Spindle suggestion—Transverse hole to pin undercutting tools. W. D. Pershore. *58
Entropy. 620
(Set screws.) C. Kaufmann. *621
—Spindles, Key slots in. W. J. B. *991
—Standardizing shanks; keys; tangs; tapers. F. Oyen. *296
R. Brown. 774
A. H. Matson; A. Frederic. 993
—Steel, Drilling hard, using hollow lap. S. W. Green. *729
—Sub-drill, Multi-spindle. F. H. Stead. *414
—Support, Drill, Chucking machine. A. M. Peck. *445
—Tools, Drill-press, for loco. work. *89
—Triple-geared upright drill, Hilbert. *548
—Turret-drilling attachment for drill press or lathe. Patterson Tool & Supply Co.'s. *960
—Twist drill, Lincoln & Williams "Yankee." *924
—Twist drills, Backing off. *38
—"Use-em-up" drill socket, American. *1001
—Using broken drills—Rockford method. *945
—Wabble drill. E. A. Dixie. *24
John E. Sweet. *733
F. Sellit. *734
—Why does it cut—Hardness? 405
M. B. Stauffer, F. S. Thompson, E. E. Neal. 581
H. Fletcher. 625
Drive, Dieterick universal. F. H. C. *838
Drive, Two speeds from constant-speed. *307
Driving tools—Making Simplex autos. *603
Drop forging. See "Forging."
Drums for hoisting engines, Molding. *426
Drying machine, Blue-print, Toerring. *853
Dust caps, Machining. *727, *971
Dynamometer, Auto. Club's Wheeler. E. F. L. *111
Dynamometer, Magnetic absorption. C. M. Garland. *162

E

Ebonite, Recessing tool for. J. Herbert. *58
Eccentric chuck for boring tool. Jared. *848
Eccentric, Patched. C. Hamer. *215
Eccentric sheaves, Machining. J. Essex. *660
Eccentric-turning attachment. C. H. K. *987
Eccentric turning job. E. A. Johnson. *688
Eccentrics, Expanding arbors for. *393, *956
Echoes, Oil-country. W. Osborne. 23, 128, *194, 242, 341, 582, 517, 562, *723, *899
Economy in machine design. S. H. Bunnell. 428
EDUCATION.
—Apprentice vs. machine-operator training; married men, etc. 205, 280, 470, 661, 695, 772
—Co-operative engineering education, Cincinnati. 180
(Mathematics.) E. F. Du Brul. 290
(Mathematics.) Instructor. 407
(Natl. Met. Tr. Asso.) 555, 710, 841
(Another phase.) 920
—Engineer as a man of affairs. 921
—Engineering and industrial education. F. A. Geier, H. Schneider et al. 710, 555
—Evening-school shop work. E. R. Markham. 99
—India, Industrial development. 590
—Industrial education—Are we taking hold at wrong end? 776
—Industrial education, N. A. Mfrs. and. 842, 844
—Industrial education—Winona Inst. 294, 328, 554, 711
—Industrial Education, Natl. Society. 222, 256, 590, 693, 776
—Industrial efficiency, Individual. 363
—Industrial training; Mass. schools. Entropy. 427
—Machine-tool design Worcester Polytechnic. E. H. Fish. *932
—Progressive shop education. F. A. Waldron. 522
—School of toolmaking wanted. 294
—Schools, German trade. 362, 624, 664, 711, 920, 995
—Shop training for engineers. Entropy. 248
I. F. Martin. 806
—Shops do commercial work? Can school. J. H. Gill. 110
(State-supported schools.) 256
(Actual Trade school.) F. A. Pratt. 342
(Disposal of products.) T. D. Hayes. 624
(Public industrial schools.) T. D. Hayes. 693

PAGE

Entropy. 770, 806, 995
E. H. Fish. 932
(Artisan School.) J. E. Sweet. 993
—Tech. courses, Increasing length of. 404
—Tech. graduates and tool trade. Instructor. 353
Efficiency, Industrial, of individual. 362
Elastic limit, Limit of proportionality and. H. Hess. *397
ELECTRICITY.
—Drills and motors, Foreign portable. *54
—Driving, Electric, Notes—Motor selection. P. E. Severance. 368
—Electro-plating, Cleaning work for. 609
—Engineers, McGraw Handbook for. †665
—"Engineering, Elec., Introduction." H. H. Norris. †627
—Hardness tester, Hughes' electromag. E. F. Lake. *557
—Flat irons in engine repair. 15
—Furnaces, Steel. Héroult, Stassano, etc. *479
—Furnaces, Steel-treatment. E. F. Lake. *488
—Generating sets, Sturtevant. *923
—Lightning arrester, Electrolytic, Westinghouse. *592
—Motor-belt tightener, Crocker-Wheeler. *331
—Motor drive, Screw-machine, Natl. Acme. *884
—Motor drives, lathe and miller, Le Blond. *108
—Motor for Chapman ball-bearing tests. *133
—Motor frame, Street-car, Machining. P. Fenaux. *384
—Motor-lamination punchings, Compound dies for. K. S. Allen. *561
—Motor-starting rheostats, Westinghouse. *475
—Rolling-mill drive, Ill. Steel Co.'s. Westinghouse—Equalizer, motors, etc. *51
—Sand-blast machine as "generator." B. O'Reilly. 172
—Winding lathe. Greaves, Klusman & Co.'s. *698
Elevating material, Power cost. R. Hoyt. 178
Elevator, Odd old. *255
Ellipses, Diagram for radii of arcs for drawing. S. J. Teller. *211
Elliptic templets. W. Gribben. *260
Emery wheel. See "Grinding."
Enameling iron goods ivory color. 609
End-mill for hexing. E. Viall. *604
End-mill, Inserted-blade. H. E. B. *769
Ends of work, Finishing. R. D. Morse. *732
ENGINE.
—Alcohol-Fuel Tests, Lucke, Woodward. †143
—Alcohol vs. gasolene—Govt. tests. 593
—Allis-Chalmers Co.'s rotary-planer work. *979
—Auto. engines, Simplex, Making. *599
—Brasses, Making auto. *395, *1001
—Creusot works, Engine building. *860
—"Engine-Room Chemistry." A. H. Gill. †473
—Gas engine, Carnegie Co.'s. 94
—Gas-engine construction, New features—Riverside double-acting tandem engine at Watson-Stillman plant—Valves; cylinders; pistons, ignition; pneumatic starting device and control, etc. G. W. Malcolm. *821
—"Gas Engine." F. R. Hutton. †850
—Gas-engine cylinders, Machining Reid Co.'s Oil Country. W. Osborne. *194
—Gas-engine repairs—Bearing play, pinning wrist pin in place; keying fly-wheel; oiling wrist pin; tool for recutting valve seats. C. Kaufmann. *323
—Gas-engine shafts. W. H. Booth. 575
—"Gas Power." F. E. Junge. †850
—Gasolene-engine cams, Making. *308, 584
—Gasolene-engine cylinders, Machining Cadillac. *113
—Generating sets, Sturtevant. *923
—Oil engine, Starting—Engineering ethics. W. Alton; A. P. 141, 326
(Locomotive.) D. N. Keyes. 254
—Oil engines, Novel small. A. S. Ager. *934
—Hoisting engines, Quarry—Brakes. H. L. Bunhus. 779
Wm. Whaley. 954
—Rolling-mill engine, Carnegie Co.'s 25,000-h.p. Allis-Chalmers. Jas. Tribe. *745
—Success as reliability test. 218
—Traction-engine story. J. G. Dornbirer. 742
Engineer as a man of affairs. 921
Engineers, A. S. M.—Jan. meeting; Dixon on car lighting. 143
—Publication of Proceedings. 590
—Towne's gift to library. 218
—Gas-power section. 295
—Conserving natural resources; meeting plans. 665
Engineers, Shop training for. Entropy. 248
I. F. Martin. 806
Engineering ethics. 141, 254, 326
"Engineering Index Annual." †777
"Engineering Reminiscences." C. T. Porter. †591

PAGE

"Engineering Work-Shop Practice." Allen. †31
English lathe design. *105, *173, 287, *466, *536, *576, 734
English tools and methods. J. W. Carrel. *389, *416
Epicyclic train, Spencer screw machine. *799
Epicyclic wheel trains, Calculations. A. W. Jones. *249
Equalizing set, Illinois Steel Co.'s. *51
Eraser for Higgins' ink. E. W. Cleveland. 659
Eraser, Motor-driven, Coates. *961
Esser, Herman, Death of. 696
Ethics, Engineering. W. Alton. 141
D. N. Keys. 254
A. P. 326
Evening-school work. E. R. Markham. 99
Ewart, Wm. D., Death of. *892
Exception system of management. 472
Expanding tool. C. B. Kirkham. *529
Expansion in hardening. See "Hardening."
Expense analysis. 106
Exporting discussed before N. A. M. 842
Extensions on taps, etc. G. M. Diehl. 735

F

Face plates, Toolmakers'—How drilled. T. McCabe. *687
Facing bar for opposite side of hole. H. T. L. 692
Facing bar, Weller's "Neverstick." *407
Facing centered work. R. D. Morse. *732, *773
Facing cutter, Double. C. P. H. *689
Facing loco. pedestal jaws, Underwood machine. *552
Facing tool, Double. W. R. G. *360
Factor of safety in ball bearings. G. T. Rennerfelt. *720, 817
Factors of safety, Personal. W. Osborne. 128
Factory sites, Unfortunate. 446
Featherways in saw collars, Milling. W. M. L. *656
Feed, Automatic lever, for die. *174
Feed, Magazine, Chain-stud recesser. *17
Feed, Rack, Schellenbach lathe. *826
Feeds, Air, large Bement planer. *7
Ferrite—Microscopical examination. *492
Ferro-titanium. 919
Fiber friction washers. H. A. Burt. 415
Fiber, Red, Wearing qualities. E. D. Gagnier. 879
File efficiency. M. J. Grange. 942
Filing AMERICAN MACHINIST. W. C. McLeod. *726
Fillets, Crank-shaft, Machining. *833
Fine adjustment for boring bar. *434
Fire prevention, Natl. Asso. of Mfrs. on. 844
Fits, Drive vs. shrink, G. Schneider. *398
W. L. McLaren. 774
Fits, Ground, Limits. Gould & Eberhardt's. *374
Fittings for high-pressure air. Haight and Batcheller. *633, *905
Fixture. See also "Jig," "Milling," "Planing," "Grinding," "Shaper," "Lathe," "Assembling," etc.
Fixture for holding square pieces. *729
Fixtures for special work. H. C. Barnes. *672
Fixtures, Pneumatic. M. E. Service. *867
Flanges, Pipe, Patterns for special. F. W. Barrows. *608
Flanging press, Boiler-sheet. W. J. Withem. *682
Flat irons used in engine repair. 15
Floor-plate planers, Rotary twin. Allis-Chalmers Co.'s. Bement-Miles. *979
Fluting planer, Woodward & Powell. *700
Fly-cutter arbor. R. G. D. *657
Fly-wheel balancing — Magnetized weights. *728
Fly-wheel boring mill, Niles. *412
Fly-wheel experiences. F. E. Booth. 521
Fly-wheel, Gas-engine, Keying. *323
Fly-wheel, Large Boring-mill rig for. P. Fenaux. *953
Fly-wheel with steel-plate webs. J. T. Athey. *246
Fly-wheels, Auto., Machining on Grisholt lathe. *167
Fly-wheels, Equalizer. Ill. Steel Co.'s. *52
Fly-wheels, Gas-engine—Pond turret lathe. *795
Fly-wheels on countershafts. J. R. Godfrey. 925
Follow rest, Schellenbach lathe. *832
Food, Pure, Natl. Asso. of Mfrs. on. 844
Foreman of No. 6. W. Osborne. 242
Foreman, Working, What is? J. Cran. 990
Foremanship, Efficient. 66
Foremanship. C. A. Marston. 462
Foremen, Educating. F. A. Waldron. 522
Foremen, Instructions for. 106
Foremen, Mare Is. H. A. Evans. 569, 610, *645
(Meetings.) Entropy. 995
Foremen, Machine-shop. 882
Forges, Oil-fired, Mare Is. *155
Forging, Drop, Mare Is. H. A. Evans. *456
Forging high-speed steel. E. Viall. 314
R. Langlin. 808

PAGE

Forging steel. E. F. Lake. 512
Former attachment, Lathe, Mossberg. *332
Forming-cutter problem, Circular. *443, *810, *880
Forming-tool holder slide for round work. J. Braum's, R. Grimshaw. *991
Forming tools, Circular. J. C. Richardson. *845
Forming tools, Screw-machine. Goodrich, Stanley. *299
McK. *775
Forney, M. N., Death of. 143
Foundations—Bolting planers, etc. 137, 250, 325, 355, 403, 437, 445, *535, 662, *670
FOUNDRY.
—See also "Pattern," "Blowers," "Core."
—Blast-furnace casting. W. H. Booth. 253
—Burning new flange on double motor cylinder. D. Whyte. *425
—Car-wheel chill, New. *425
—Casting faces on valve seats. W. H. Bewers. *621
—Casting nuts in. Barnes pat. *70
—Castings, Steel, Vanadium in. E. F. Lake. *532
—Core tapers, Wax. J. B. Sperry. 849
—Cores, core sand and core-making machinery. G. H. Wadsworth. 74
—Creusot works. J. B. Van Brussel. *857
—Cupola demonstration. Ballot Co.'s. 812
—Dies, Wire-drawing — McFarland foundry. *718
—Iron and castings for piston-ring blanks. A. Manchester. 684, 915
—Machine Tool Builders' committee. 841
—Molding drums for hoisting engines; sweeps. J. F. Hart. *426
—Molding hydraulic cylinder. D. S. Fides. *818
—Molding mower wheel. A. D. Mundy. *537
—Molding with machinery; bench work; vibrator; mechanical lifting. J. H. Hart. 93
—Molding 3-parted job in 2-part flask. W. W. McCarter. *644
—Molding 3-way reciprocating valve. W. W. McCarter. *18
—Molding 4-way stand-pipe. G. Buchanan. *312
—Oil furnaces, Mare Is. *161
—Steel casting. E. F. Lake. 510
Frame, Machining car-motor. P. Fenaux. *384
Fraud—Operating an old game. 777
Freight charges, Machine Tool Builders on. 841
Friction and lubrication. J. T. Nicholson. *46, *80
Friction of cams. Con T. Wise. *196
Fuel resources, Conservation of our. 665
Furnace, Carbonizing. Am. Gas Furnace Co.'s. *263, *501
Furnace, Electric hardening. Even heating of—Steinthal's paper. G. B. Waterhouse. 788
Furnace for high-speed steel. J. Steel. *89
Furnace, Hardening. H. T. Ashton. *453
Furnace, Rivet-heating. E. Balbach. *262
Furnaces—Barium chloride for hardening. *519
Furnaces, Oil, Mare Island—Boiler forge, reverberatory, angle-heating, etc. *153
Furnaces, Steel-making. E. F. Lake. *477, 510
Furnaces, Steel-treatment. E. F. Lake. *487, *501
Fuse-bushing tools and output. *37

G

Gage. See also "Caliper," "Micrometer," "Vernier," "Size block," "Indicator."
Gage, Backing-off. S. Peters. *583
Gage, Bevel-gear. A. H. Gang. *930
Gage, Bristol recording water-level. *258
Gage, Depth, German vernier caliper and. New Metal Tool Steel Co.'s. *259
Gage for monotype inspection. *120
Gage for rod ends. J. S. Scott. 727
Gage for setting gear cutters and work. W. George. *102
Gage-grinding machine, Waltham. *333
Gage, Indicating, for rolls. W. E. Malo. *399
Gage, Taper, Accurate; setting disks. C. C. Stutz. *458
Gage, Taper—Scraping, testing. N. B. Chace. *935
Gage work—Test indicator. F. Rattek. *441
"Gages and Gaging Systems." J. V. Woodworth. †696
Gages, Block, Box of. G. B. Howe. *403
L. F. Charles. *914
Gages—Expanding-plug; Contracting-ring. Taylor's. *391
Gages for Chapman ball bearings. *130
Gages for dividing-head tests. *13
Gages for machining crank-shafts. *833, 835
Gages for planing V's in multiple. *907
Gages, Inspection, for motor-frame casting. *384

PAGE

Gages, Snap, Curious. F. S. Brown. *231
Gaging—Bullard standard size blocks. *713
Gaging dovetails and V's. F. H. Scheu. *650
Galvanizing, Oil fuel in, Mare Is. *160
Gas, Case-hardening steel with—American gas furnace. E. F. Lake. *263, *501
Gas crucible furnace, Regenerative. *479
Gas engine. See "Engine."
Gas furnaces, Steel. E. F. Lake. 487, *501
"Gas Mfr., Chemistry of." H. M. Royle. †777
"Gas Power." F. E. Junge. †850
Gas-power section, A. S. M. E. 295
Gas to replace saw. R. Grimshaw. 320
Gasolene, Alcohol vs.—Govt. tests. 593
Gasolene, Reclaiming — Burroughs' Eaton still. 891
GEARING.
—Angle drive in small space. J. W. Greene. *398
—Bevel-gear cutting, Arbors and gages for. A. H. Gang. *930
—Bevel-gear pattern, Making. J. R. L. *618
—Bevel-gear planing attachment for Cincinnati shaper, Mill's. *642
—Bevel-gear teeth, Attachment for sawing. A. E. Owen. *291
—Bevel gears at once, Cutting two. *337
—Bevel gears—Contract job—Reducing cost; drop forging, chucking, etc. F. E. Brown. *709
—Bull wheels, large Bement planer. *8
—Change-gear box, New Haven. *183
—Chucking warped gears. Ste' A. A. E. P. L. *615
—Cutter, Gear, Cincinnati. *702
—Cutter, No. 3 automatic gear. Eberhardt Bros.' Mach. Co.'s. *147
—Cutter, Gear, Small automatic, Waltham. *883
—Cutter-setting gage. W. George. *102
—Cutter, Spur-gear, Eberhardt Bros. *700
—Drive, Geared, Queen City shaper. *737
—Drive, Universal Dieterich. *838
—Emergency gear-cutting job. S. P. Kane. *355
—Epicyclic train, Spencer automatic screw machine. H. S. *799
—Epicyclic wheel trains—Calculations; Baker compound planetary. A. W. Jones. *249
—"Formulas." B. & S. Mfg. Co. †997
—Gear boxes too strong. J. R. Godfrey. 255
—Gear with removable rim, Nuttall. *960
—Headstock, Hulse & Co.'s. *909
—Helical or spiral gears, Direction of rotation and thrust of. W. F. Zimmermann. *866
—Hobber, Worm-wheel, Le Blond. *897
—Hobbing bevel gears with Bostock's taper hob; special machine. E. Gregory. *344, 805
V. Gartside, J. A. Svensson, H. H. Wilson. *804
—Hobbing machine and dividing head tests, cleaning worm gears, etc., Cincinnati. *10
—Hobbing machine, Gear. Adams Co.'s. *885
—Hobbing machine, Geared, German. *791
—Hobbing machine 15 years old. P. E. Kleineberg. *212
—Internal gears on shaper, Cutting—Harthan's device. F. H. C. 574
—Lathe, Schellenbach. Morris Fdy. Co.'s. *826
—Motor drives, Le Blond. *108
—Oval fitting to shaft. *148
—Pinion cutter, Automatic, Waltham. *184
—Planer-gearing design. Entropy. *877
—Planing attachment. A. E. Robinson. *941
—Plaster of paris in repair. 392, 771
—Rack cutter, Gould & Eberhardt. *545
—Racks, Hobbing. Cheney patents. *573
—Reversing mechanisms. L. D. Burlingame. *189, *234
—Speed-changing device. E. S. P. *586
—Steel spur and bevel gears from stock, Boston. 553
—"Stub-Tooth Gear." Fellows Co. †107
—Teeth, Gear, Rounding ends. J. F. Wells. *580
—Teeth, Safe working loads for; formulas, contact, strength, hardness, wear, etc. C. H. Logue. *95
—Tooth-chamfering attachment, "Long-Arm." *331
—Tool-rounding machine; cutting internal clutch gears in press—Simplex Auto. Co.'s work. *599
—Tooth-rounding machine, Lejeune. W. F. Groene. *942
—Truing gear in hand lathe. *938
—Worm-gear drive, New arrangement of. T. A. Weston. 140
—Worm gears, Making small. E. C. O. *216
—Worm-wheel hobber, Auto. Eberhardt Bros.' *998
General Electric's pay-roll system, Lynn. *348
Generating sets, Sturtevant. *923

PAGE

German trade schools. 362, 624, 664, 711, 920, 995
Germany, Interesting machines from. *790
Germany's industrial activity, Factors in. L. J. Auerbacker. 678
Get-together meetings. J. R. Godfrey. 925
Get what you earn, etc. Con T. Wise. 284
Getbusygraph. G. H. Wallace. *926
Gibs, Making cast-iron. A. Ehrhardt. *576
Gland, Packing, Tool for. W. T. H. *911
Glass as flux for brass. 695
Glue heaters, Electric. Md. Steel Co.'s. *200
Glue pot, Electric G. E. Co.'s. *448
Gluing auto. steering-wheel rims, Press for. M. E. Grand. *617
Government shops. H. A. Evans. *568, *610, *645
Graduating machine, Landis Co.'s special. H. F. Noyes. *150
Graining machine, Potter ball-bearing. *310
Graphical charts, Construction. J. B. Peddle. *753
GRINDING.
—Adjustment, Simple. E. A. Dixie. *989
—Ball bearings for high speed. 907
—Ball bearings, Grinding Chapman. *130
—Cam-grinding rig, Premier auto. *712
—Center grinder Electric, U. S. *697
—Crank-grinding machine, Landis—Hand-wheel mechanism; wheel-truing device. E. A. Shriver. *725
—Crank-shafts, Multiple-throw—Norton Co.'s method. J. C. Spence. *833
—Cutter and reamer grinder, Wells motor-driven. *544
—Cutter grinder, Wood universal. *330
—Cutter, Large-radius milling, Fixture for grinding. C. E. Chamberlain. *879
—Cutters, Boring-bar, Bullard grinder for. *713
—Cutters, Grinding formed. H. T. Ashton. *455
W. H. Booth. 605
—Cutters, High-speed steel, Recutting. W. Alton. *830
—Cutters, Using bevel side of wheel in grinding. E. S. Williams, G. E. Quinn, P. W. Abbott. 248
G. W. Goodchild. 401
B. F. Newcomb. 431
J. E. Ramopon. 537
Nero. 775
—Cylinders, Thompson attachment for grinding auto. *421
—Disk grinder, Gardner combination. *33
—Drill and cutter grinder, Combined. Wilmarth & Morman Co.'s. *890
—Drills for cock-key centering, Jig for grinding. E. Viall. *247
—Edge grinder, Automatic. Safety Emery Wheel Co.'s. *739
—Fixture for grinding ball joints. W. A. Raymur. *28
—Fixture for holding square pieces on magnetic surface grinder. Tool Designer. *729
—Fixture, Simple grinding. S. W. Mills. *213
—Gage-grinding machine, Waltham. *333
—Grinder, Blevney's new type—Use of emery-cloth belts—Machines for hammer heads and drop forgings. F. H. C. *419
—Grinder for large tools, Bridgeport. *149
—Grinder, Universal edge-tool. Mummert, Wolf & Dixon Co.'s. *70
—Grinding and disk polishing machine. Safety Emery Wheel Co.'s. *364
—Grinding machine, Churchill vertical. *389
—Grinding-machine troubles — Improper speeds; wheels not true; wrongly belted; magnetic chucks. J. N. Heaid. *560
Stoever Co. 809
—Grinding-room system. W. H. Taylor. *123
—Grinding vs. cutting by emery wheels producing ribbon; magnified chips. C. H. Norton. *451, 587
H. A. Richmond. *771
(Without wheel traverse.) H. F. Noyes. 807
—Hollow mills, Grinding. Conrad. *622
—Internal grinder. Heald Mach. Co.'s. *542
—Lathe into internal grinding machine, Converting. E. E. Eisenwinter. *290
—Mills, Butt, Grinding. E. Viall. *605
—Monotype-mold making; special grinder. *117
—Oilstone scraper sharpener, Mummert, Wolf & Dixon. *544
—Piston-ring and disk grinder, Saxon. *552
—Planers, Testing and using, in Landis grinder shop. E. A. Shriver. *671
—Profile-grinding attachment, Schuchardt & Schütte's. *963
—Pulleys, Grinding cone, by Landis Co.; radial truing fixture for wheel. J. H. Hollinger. *230
—Reamers, Radius fixture for. *87
—Reversing. L. D. Burlingame. *189, *234
—Rubber, Grinding. 623, 752
—Saws, Grinding milling. E. Viall. *462
J. O. Surface. 773
—Spherical grinder, Rivett, for ball cups of Dock engine. *597
—Springs, Double-ended machine for grinding ends. Hammett Co.'s. *465

PAGE

—Surface grinder, Walker No. 3. *144
—Surface grinder with cutter, drill and reamer attachments, Wilmarth & Morman. *550
—Taps, Backing off, Rig for. *38
—Time required for cylindrical—Norton example, etc. F. H. Colvin. *422, *526
—Tools, Injuring in grinding. J. S. Dyson. 774
—Universal tool-room grinder, Le Blond. *888
Guarantees, Accuracy, Richards & Co.'s. *389
Guide pins, Fitting. P. F. *356
Gun-barrel mandrel, Making. E. C. Peck. *429
Gun, Dynamite—Rapieff joint. *640, *995
Gun making, Rapid-fire, Watervliet. *39
Gun shops, Creusot works. *862
Gun, Shot, barrels, Reamers for choke boring. E. N. Amory. *614
Guns, Cutting-off tool for. *104

H

Hack saw. See "Saw."
Hammer-head grinding with belts. *420
Hammer, Pneumatic. C. L. Hooker. *586
Hammer, 100-ton, Creusot works. *857
Hammers, Drop, Safety device. R. Grimshaw. *102
Hammers, Steam, with solid anvil, Buffalo "Bell." *851
Hand-turning operations. J. Lomas. *938
Handles, Tool, Bluing. F. Webster. 985
Hanger box for grease or oil. Olney & Warrin's. *738
Hard times, Individual efficiency in. Entropy. 34
Hardened tools, Straightening. T. Foot. 649
Hardening, Barium chloride for. O. M. Becker. *519
Hardening, Bushings expanded in. J. Bomby. *356
Hardening, Case, New applications. P. C. Osterman. 237
Hardening, Case, Steel, with gas, etc. E. F. Lake. *263, *497
Hardening cutting tools. J. Sutherland. 589
Hardening—Cyanide dangers. S. A. Nyde. 457
Hardening drop-hammer die made of poor steel. K. Chambers. 584
Hardening—Fish-oil smell. E. Viall. 794
Hardening furnace, Electric, Even heating of—Steinthal's paper. G. B. Waterhouse. 788
Hardening—Furnace for high-speed steel. *89
Hardening high-speed steels. E. Viall. 314
R. Langlin. 808
Hardening high-speed steel cutters; furnace. H. T. Ashton. *453
W. H. Booth. 605
Hardening high-speed steel—Charred leather packing; forming tools, etc. E. R. Markham. 134
(Using putty.) E. S. Wheeler. 660
Hardening lattice-bar punches. E. A. Dixie. 537
Hardening methods of large shop—Steels, using up old dies; lead baths; quick work; high-speed furnace; reamers; composite die, etc. C. R. Claver. 126
G. School. 661
Hardening multiple-throw crank-shafts, Holder for. R. B. B. Little. *962
Hardening small pieces—Tank. Nene. *57
Hardening rubber tools with cyanide. G. Harfmann. 881
Hardening steel. E. F. Lake. *491
Hardening, Steel alterations in. J. E. Storey. *277
(Taps distorted.) A. Gwaikokujin. *359
(Contraction, etc.) H. Fletcher. 442
E. T. Strong. *463
(Pin gages.) H. C. Gunson. 735
See also "Iron."
Hardening, tempering, etc., tools. J. Steele. 673
Hardening thread dies. Goodrich and Stanley. *380
Hardening—Using oil. E. R. Markham. *63
(Cutters; press dies.) J. Steele. *619
(Nut-forming cutter.) E. Viall *955
Hardness and cutting power, Drill., 405, 581, 625
Hardness in steel and its variations; use of scleroscope, etc. A. F. Shore. *675
Hardness testing. E. R. Markham. 223
(Standard hardness.) W. H. Fleet. 350
E. F. Lake. *507
(Hughes' electromagnetic tester.) E. F. Lake. *557
Harveyizing steel. E. F. Lake. 263, 498
Haste, Profitless. 627
Headstock, All-geared, Hulse & Co.'s. T. M. Lowthian. *909

PAGE

Heat treating, Steel alterations in. J. E. Storey et al. *277, *359, 442, 463, 735
Heat treatment of steel. E. F. Lake. *486
Heating, Growth of iron by. 432, 686
"Heating, Practical Steam and Hot Water." A. G. King. †959
Hex nuts, Milling. F. C. P. *728
Hexing, etc., Vertical index fixture for. *731
Hexing valve bodies. E. Viall. *604
"Hill Kink Books." Colvin and Stanley. †405
Hobber, Gear, 15 years old. *212
Hobbing bevel gears with Bostock's taper hob; special machine. E. Gregory. *344, 805
V. Gartside, J. A. Svensson, H. H. Wilson. *804
Hobbing die chasers. E. A. Dixie. *653
Hobbing machine and dividing head tests. Cincinnati M. M. Co.'s. *10
Hobbing machine, Automatic worm-wheel. Eberhardt Bros. *998
Hobbing machine, Gear. Adams Co's. *885
Hobbing machine, German geared. *791
Hobbing machine, Le Blond, for index worm wheels. W. F. Groene. *897
Hobbing racks. Cheney patents. *573
Hogging machines for rolls. E. F. L. *893
Hoist, Electric, Yale & Towne. *852
Hoist, Elec., "Shepard." Genl. Pneu. Tool Co.'s. *32
Hoist-frame housing, Patching. F. H. Whitney. *137
Hoist, The Climax. *1000
Hoists—Crane lifting-magnets. *528
Hoisting engine, Dense-air. 626
Hoisting engines, Brakes for. H. L. Bunhus. 779
Wm. Whaley. 954
Hoisting engines, Molding drums for. J. F. Hart. *426
Hoisting hooks—Diagram. A. Pederson. *170, 587, 181
Holder. See "Tool," "Reamer," "Tap," "Micrometer," "Dies," "Press," "Crank-shafts," "Air," "Jig," etc.
Hole, Square, Expanding. E. A. Dixie. *845
Holes crosswise in round work. *25, *661, 733, 954
Hollow mill, Inserted-tooth. F. G. Wilson. *1003
Hollow mills for screw machines. Conrad. *622
Hollow mills. Goodrich and Stanley. *209
Hooks, Hoisting—Diagram; Bach's formula. A. Pederson. *170, 587, 181
Horses compared with steam engines. 307
Hub work, Loco., Cat heads for. *87
Hydraulics, Removing shanks by. *177, 355, *585, *880
"Hydraulics, Treatise on." W. C. Unwin. †68

I

Illinois Steel Co.'s electric drive. *51
Illinois Univ. bulletins. †142, †363, †813
Impact-testing steel. E. F. Lake. *507, 509
Incorporation, National, N. A. M. on. 843
Index die for armature punchings. K. S. Allen. *946
Index drilling of caps. G. Huber. *467
Index plate, Antique. B. D. Whitney's. *320
Index plate drilling machines, LeBlond and Hendey. *750
Index plate, Sector for dividing holes in. M. H. Ball. *103
Index plates of Landis graduating machine. *151
Index wheels, Le Blond hobber for; testing worm-wheel. *897
Indexing—Dividing-head tests. *12
Indexing—Gridley multi-spindle lathe. *165
Indexing job, Nice. E. W. Richmond. *354
C. H. Erb. *880
Indexing 5-min. vernier. H. K. Harring. *214
India, Industrial development. 590
Indianapolis, Industrial education. 294, 328, 554, 711
Indicating gage. W. E. Malo. *399
Indicator, Dial Test, Using. N. B. Chace. *935
Indicator, Electric bell and. A. D. Allen. 140
Indicator, Inspecting, for Ellis machines. *904
Indicator, Inspecting tools with. J. H. Boulet. 438
Indicator, Test. E. M. King. *245
Indicator, Test. F. Rattek. *441
Indicator, Test. G. T. Aldin. *469
Indicator, Test. R. A. Almond. *534
Individual efficiency in hard times. Entropy. 34
Industrial education. See "Education."
Inspecting indicator for Ellis machines. *904
Inspecting tools with indicator. J. H. Boulet. 438
Inspection gages for motor-frame casting. *384
Instructions for foremen. 106
Instructions, Shop. H. A. Evans. *610, *645
(Foremen's meetings.) Entropy. 995
Invention, Wrapping-machine. J. G. Dornbirer. 793
Iron—Blast-furnace casting. 253

Iron, Cast, Brazing. F. L. Nichols. 64
Iron, Cast, Growth by heating. A. E. Outerbridge et al. 432, 686
Iron, Cast, Vanadium in. R. Moldenke. 297
Iron for piston-ring blanks. A. Manchester. 684, 915
Irons, Flat, in engine repair. 15

J

Japan, Trade with. C. A. Francis. 872
Jaw faces, Three, milled at once. *176
JIG.
—Boring without laying out. H. K. Krum. *321
(Limit dimensions; holding work, etc.) P. S. Prince. *358
G. E. G., F. H. Sander. 402
O. Burt. 403
(Stops for miller.) Cy. Press. *433
(Master-plate work.) *588
H. P. McCabe. *623
J. G. Vincent. 796
—Bushings, Movable. A. J. Baker. *101
M. R. Kavanagh. *175
P. Princeps. 287
L. Haas. *443
C. I. Innis. *471
E. A. Dixie. *735
—Cross-drilling tool, Landa's. *406
—Cylinder work, Gas-engine. W. Osborne. *194
—Cylinders, Jigs for. Alley & Maclellan's. *272
—Dowel holes, Roberts jig for. *855
—Drill jig for cotter-key hole in bolt; jig for oil hole and shield on 2-spindle press. F. Sellit. *734
—Drill jig for tool bracket. *22
—Drill jig, Piston-ring. F. E. Booth. *731
—Drill jigs, Three. R. Grant. *437
—Drilling ball ends. R. Grant. *468
—Drilling balls. S. W. Green. *687
—Drilling spanner holes. J. E. Anderson. *849, *953, *986
—Eugene brasses, Making. R. Whaley. *1001
—Fixtures for drilling and milling bracket. H. C. Barnes. *672
—Gibs, Milling cast-iron. A. Ehrhardt. *576
—Hole locating with vernier. G. E. Gay. 402
—Jig making in large mfg. plant—Leaf jigs; methods of work. H. C. Barnes. *566
—Latches, Jig. R. D. Morse. *732
—Micrometer head; facing clock pinions. G. D. H. *692
—Motor-frame, Car, Drilling and boring boring jigs for. *385
—Piston-ring jig. W. J. B. *948
—Piston-ring jigs. W. C. Chinneck. *216
A. E. Heming. *357
—Planing jig, Landis. H. F. Noyes. *325
—Pneumatic fixtures. M. E. Service. *867
—Simple jig for locating holes. C. H. Erb. *880
—Simplex Auto. Co.'s jigs for water-jacket covers, crank cases, etc. *599
—Stud-drilling jigs. P. W. Abbott. *393
—Sub-drill, Multiple-spindle. *414
Job-shop vicissitudes. J. G. Dornbirer. 525, 667, 742, 747, 793, 837, 863, 937
Job-shop experience. Y. Ziegler. 992
Johnson, Fred A., Death of. 921
Joint, Pin universal, Kinsler-Bennett. *367
Joint, Rapieff flange. B. C. Batcheller. *640
F. W. O'Neil. *995
Joint, Universal, Kinsler-Bennett ball-bearing. *258
Joint, Water-tight sheet-metal. R. A. Anderson. *729
Joints and fittings for high-pressure air. Haight and Batcheller. *633
F. W. O'Neil. *995
Joints, Ball, Grinding fixture for. W. A. Raymur. *28
Joints, Universal. J. R. Godfrey. 925

K

Kelvin memorial meeting. 142
Kerosene burner for shrinkage heats. *241
Key, Barth, Driving arbors, etc., by. *296, 774, 993
Key hole, Cotter, Drill jig for. *734
Key slots in drill spindles. W. J. B. *991
Keys, Centering brass cock. E. Viall. *247
Keying, Gear-box—Speed changing. *586
Keyseats, Cutting four, on miller. F. C. P. *728
Keyseating hubs—Extending slotter. *241
Keyseating mandrel. H. B. Robinson. *326
Keyseating tool, etc., Combination. *258
Keyway depth, Table for total. C. W. Bennett. *179
Keyway in hard screw, Planing. J. Bell. *177
Keyways in saw collars, Milling. W. M. L. *656
Keyways, Planing, in shaper. C. L. Goodrich. *767
"Kink Books, Hill." Colvin and Stanley. †405
Kneeland Machine Co., Work of. *893
Knockout fixtures, Drill-socket. H. T. Green. *659
Knowledge, Specific, as an asset. 446
Knuckles, Steering—Making Simplex autos. *603
Kundtz' oil-handling plant. *42

L

Labor conditions in Canada. 166, 403
Labor, Govt. shops. H. A. Evans. *568, *610, *645
Lacing, Leather-belt, Measurements in. 964
Lamp, Arc, General Electric. *885
Lamp, Enclosed-arc, Die for magnet-head punchings. J. F. A. Vogt. *168, 622
Lamp-Filament Tests. T. H. Amsine. †363
Lamp socket that locks, Gen'l Elec. *551
Lanston Monotype Co.'s work. *77, *117, *788
Lap, Hollow—Drilling hard steel. *729
Lapping fixture. F. W. B. *848
Lapping machine, Novel. Bogert's. *786
Lapping operations, Lanston Co.'s. F. A. S. *117
LATHE.
—See also "Screw machine" (under "Screw,") etc.
—Antique lathes. B. D. Whitney's. E. A. Dixie. *317
—Armature-banding and field-coil winding lathe. Greaves, Klusman & Co.'s. *698
—Automatic lathe, Fay—Machining cone pulleys. *726
—Automatic threading lathe, etc., Fay. *339
—Automatic vs. hand lathe. W. Conrad et al. *423, 345, 469, 476, 527, 623
M. I. Francis. *917
—Ball-bearings, Lathes for making. *133
—Beds, Inverted-V and flat; English and American ways; Nicholson's views; bearings, gears, compound rests, etc. *105
John E. Sweet. *173
J. P. Wheeler. 287
Entropy. *466
F. Pike. *536
R. Thompson, J. Vose, E. A. Dixie. *576
(Wear, carriage support, screw cutting, fast work, etc.) A. I. Dodge. 734
—Belt tire drive for turning wheel journals. H. W. Jacobs. *418
—Bench-lathe schemes—Counterbore for porcelain; chuck for facing to gage; cutting small work to length; expansion chuck; tail spindles. F. J. LeCard. *244
—Buffing and polishing, Webster & Perks. *186
—Caps, Turning soft-nose. *39
—Center, Ball-bearing revolving. Taylor's. *391
—Center, Turning hard, with carborundum tool. H. F. J. 173
—Chucks, Draw-in, for engine lathe. *913
—Chucking thin work. C. Sherwood. *177
—Crank-shafts, Multiple throw, Machining. J. C. Spence. *833
—Cylinder flanges, Turning hydraulic. L. F. Charles. *357
—Cylinder-machining fixtures, Alley & Maclellan's. *271
—Cylinders and pistons, Machining small curved. *346
—Derrer universal shape attachment. *147
—Draw-in attachment. Adjustable Collet Co.'s. *187
—Drilling and tapping collars. G. Allen. *443
—Drilling in engine lathe. C. E. P. *394
—Eccentric-turning attachment for P. & W. bench lathes. C. H. K. *987
—Engine lathe, New Haven; change-gear box; taper attachment. *182
—Engine lathe, plain, Milwaukee. *853
—Engine lathe with many novel features—Schellenbach design, made by Morris Fd'y Co.—Headstock; securing any cutting speed; quick gear changing; carriage and bed; chasing threads with rack feed; taper attachment; tailstock; follow; rest, etc. *826
—Engine lathe, 42-in. geared-head Bridgeford. *364
—Forge lathe, Pond double-ended, for Mare Is. *184
—Former attachment. Mossberg. *332
—Forming-tool holder slide, Braum's. *991
—Grinding machine, Internal, Converting lathe into. E. E. Eisenwinter. *290
—Hand-turning operations. J. Lomas. *938
—Headstock, All-geared, Hulse & Co.'s. T. M. Lowthian. *909
—Indexing job. E. W. Richmond. *354, *880
—Lathe, Heavy motor-driven geared-head, Bridgeford. *738
—Lathe with all-geared head, Hamilton. *447
—Lathe, with Westinghouse motor, for loco. shops. Williams & Wilson Co.'s. *186
—Loco. wheel lathe, Heavy, Sellers *864
—Motor drives, Le Blond. *108
—Packing, Making metallic. *466, *881
—Nozzle, Boring special. F. E. Fick. *768
—Patternmakers'. Am. W. W. M. Co.'s. *147
—Patternmakers' Oliver gap lathe. C. H. Fry. *606
—Piston rings, Turning. *216, 357
—Plugs, Taper, Turning. *392, *955
—Portable 16-in., Lodge & Shipley. *883
—Projectile lathe. Firth-Sterling's Bement. *146
—Pulleys, Cone, Machining—Fay auto. lathe. *726
By Steptoe Shaper Co. *752
—Rapid-reduction lathe for car buffers, etc., Lorenz. *791
—Relieving lathe, Churchill. *389
—Rests, Roller. G. H. Handley. *988
—Roll turning, Kneeland shops. *893
—Rolls, Making wooden textile. *26
—Screw-cutting attachment for 13-in. English lathe. B. E. Church. *100
—Screw-cutting job—Driving lathe from lead screw. H. Egloff. *615
—Screws, Making accurate. Theodore. *952
—Simple and turret lathe. C. W. Sutherland. 476
—Spindle-boring lathe, Le Blond double-ended. W. F. Groene. *707
—Taper-turning attachment, Zange. *183
—Taper work, Saving time in. C. H. W. *327
—Tapping fuse bushings. *38
—Threads, Cutting V. *58, *62, 396, 139, *293, 325, 387, 534, 578, 588, 663, 880, 916
—Threading, Rapid. E. S. Williams. *467
—Time required. F. H. Colvin. *422, *526
—Turning job, Eccentric. E. A. Johnson. *688
—Turret lathe drilling fixture. Egypt. *435
—Turret lathe fixture for connecting-rod brasses. E. Beck. *769
—Turret lathe, Gridley multiple-spindle automatic. Windsor Machine Co.'s. *164
—Turret lathe, Hand—Facing and threading dust cap. P. W. Abbott. *727
—Turret lathe, Libby full-swing. International Mach. Co.'s. *259
—Turret lathe, Machining auto. fly-wheels on. *167
—Turret lathe, Motor-driven, Springfield "Fox." *547
—Turret lathe, Pond rigid, and some of its work—Fly-wheels. *794
—Turret-lathe test. N. B. Chace. *936
—Turret lathe tool for piston rings. M. R. Kavanagh. *846
—Turret lathe tools, Special. W. T. H. *911
—Turret-lathe turning tool, Machining. Alfred Herbert, Ltd.'s. A. J. Baker. *20
—Turret lathe work — Eccentric sheaves. *660
—Turret tool holder, Bocorselski's. *906
—Worms, Cutting steep-pitch, on engine lathe. W. L. K. *579
Lattice-bar punch and die. *401, 537, 881
Law — Collections — Conditional-sale form. 90
Law knowledge for superintendent. O. E. Perrigo. 41
(Off-set; costs.) Entropy. 620
Lead at low temperatures. 377
Legal. See "Law."
Lens focal distance, Chart for. *756
Level, Gravity, Deck. *742
Levels, Precision, and accurate leveling—Setting boring mill uprights, etc., by C. L. Libby; blocks for planers, by G. Langen; testing and using planers in Landis shop, by E. A. Shriver. *669, 696
Leveling a planer. J. N. Heald. *931
Leveling block, Bullard. *713
Leveling blocks, Planer. C. A. Heald. *535
Levers, Cam, for small tools. P. S. Schwim. *27
Library for draftsmen, etc. W. J. Bitterlich. 378
Lift-out, Auto., for press. G. K. *440
Lighting, Car. R. M. Dixon. 143
Lighting, Individual, for tools. H. P. Fairfield. *310
Lightning arrester, Electrolytic, Westinghouse. *592
Limit of proportionality and elastic limit. H. Hess. *397
Lining. See "Alining."
Link-belt, Way to use. S. B. Peck. *748
Links, Design of. H. W. Hunt. *443
Links in split-wheel rims, Locking. *445
Locating holes. See "Jig," etc.
Lock nut. G. G. McV. *732
Lock, Nut. P. C. Schmidt's. *854
Locking—Reversing devices. L. D. Burlingame. *234
Locomotive. See also "Railroad."
Locomotives, Air. Haight and Batcheller. *633, *995
Loewe & Co., Book of. †405
Logarithmic charts. J. B. Peddle. *756
Lubricant, Sulphur as a. 213, 441, 733
Lubricants—Machining various materials. S. J. Kelley. 674
Lubricating cutters. J. R. Godfrey. 274
L. Glaser. 622

PAGE

E. Viall. 914
Lubricating pump with Renold machine. *18
Lubricating watches and clocks—Porpoise oil. 225
Lubrication Friction and. J. T. Nicholson. *46, *80
Lucas boring machine, Building. *974

M

Machine design. See also "Design," "Drawing."
Machine design, Economy. S. H. Bunnell. 428
"Machine Design," etc. H. J. Spooner. †959
Machine equipment, Selecting. J. R. Godfrey. 345, 623
Machine-operator vs. apprentice training. 205, 280, 470, 661, 695, 772
Machine purchasers, Unnecessary calls for assistance from. Stoever Co. 809
Machine shop. See also "Shop."
"Machine Shop Work." F. W. Turner. †219
Machine-tool accuracy—Richards guarantees. *389
Machine Tool Builders' Asso. 840, 850, 9..
Machine tool design in engineering course. E. H. Fish. *932
Machine tool trade, Technical graduates and. 353
Machine tools, Antique. B. D. Whitney's. E. A. Dixie. *317
Machine tools, Automatic and hand. 346, *423, 469, 476, 527, 623, *917
Machine tools, Bolting down. See "Planer."
Machine tools—Card's time recorder. *595, 954, 994
Machine tools, English. J. W. Carrel. *389, *416
Machine tools, Lighting. H. P. Fairfield. *310
Machine tools, Power requirements of railroad. L. R. Pomeroy. *91
Machine tools, Reversing mechanisms for. L. D. Burlingame. *189, *234
Machine tools, Shorter life of. 446
Machine tools sold, Factor for keeping. 812
Machine work, Time required. F. H. Colvin. *422, *526
Machines, Prices of repair parts for. 149
Machinery Club of N. Y., F. H. Colvin. *967
Machinery Club. 68
Machinery exports, etc., U. S. 161, 179, 423, 719, 780, 862, 995
Machining steels. E. F. Lake. 516
Machinist trade, Return to. A. A. Priner. 694
Magnet-frame drilling machine. P. Fenaux. *832
Magnet-head, Arc-lamp, Die. *168, 622
Magnets, Crane lifting, German, Belgian and American. F. C. Perkins. *528
Magnets, Lifting, Manganese-steel disks for, Cutler-Hammer. 888
Magnetic absorption dynamometer. *162
Magnetic chuck, Cheap. E. J. Williams. *583
Magnetic steel furnace. E. F. Lake. *488
Magnetized balancing weights. M. B. H. *728
Management, Exception system of. 472
Mandrel for piston rings. R. B. Allen. *585
Mandrel, Gun-barrel, Making. E. C. Peck. *429
Mandrel, Wood, for tapered springs. *799
Mandrels for keyseating and babbitting. H. B. Robinson. *326
Mandrels, Piston-ring. A. E. Heming. *357
Manganese in steel. E. F. Lake. 478, *481, 498, 512
Manufacturers, Natl. Asso. of. 842, 219
Manufacturing property, Value of. 404
Mare Island Navy Yard. *153, *456, *568, 810, *645
Married men, Training. 280, 205, 661, 695, 772
Maryland Steel Co.'s shops. *198, *240
Master plates—Locating and boring holes accurately. G. H. Bert. *588
Material order lists, Gould & Eberhardt's. *374
Mathematics in engineering education. E. F. Du Brul. 290
Instructor. 407
Matrix making, Microscopes in, etc. *77. *808, *788
Measurements, Accurate scale. W. S. Romell. 239
(And machine.) Entropy. 324
Measurements, Acute vision in shop; compound microscope. A. J. DeLille. *808
"Mechanical World" pocket books. †473
Merchant marine, Natl. Asso. of Mfrs. on. 843
Methods, Different—Same jobs. S. Laurence. *654
Methods, Shop. H. A. Evans. *568, *610, *645
Micrometer, Direct fractional-reading. C. A. Kelley, *802
Micrometer head on jig. G. D. H. *692

PAGE

Micrometer, Holder for inside. A. N. Pack. *215
Micrometer nut, Tool for removing Slocomb. W. S. R. *291
J. T. Slocomb Co. *401
B. W. 773
Micrometer screws, Making in lathe. *952
Micrometer testing and setting tool. *912
Micrometer tool and nuts for clocks. *439
Micrometers, Friction stop for, Slocomb. *924
Micrometers, Repairing. G. P. Pearce. 59
Slocomb Co., G. W. Bings. 401
Micrometers with measuring bars. *354, *880
Microscope, Compound. A. J. DeLille. *808
Microscope in mfg. plant. F. A. Stanley. *77
Microcospy of steel. E. F. Lake. *492
Mill, Butt, for hexing. E. Viall. *604
Mill, End, Inserted-blade. H. E. B. *769
Mill, Hollow, Inserted-tooth. F. G. Wilson. *1003
Mills, Hollow, for screw machines. Conrad. *622
Mills, Hollow. Goodrich and Stanley. *209

MILLING.

—Butt mill and machine for hexing. E. Viall. *604
—Cams, Master. W. V. Lowe. *308, 584
—Cams, Screw-machine, Cleveland machine for milling. J. P. Brophy. *902
—Clamp, Toggle. A. E. R. *176
—Core boxes, Check-valve, Milling. *765
—Crankshafts, Multiple-throw. J. C. Spence. *833
—Cutter. See also "Cutter," "Saw," etc.
—Cutters for ball-shaped and other bearings at Kneeland shops. *894
—Cutters, Formed, Backing-off in milling machine. J. E. Poorman. *629
—Cutters, Inserted-tooth, for Milling Aluminum. S. Lawrence. *690
F. Radford. *993
—Cutters, Milling formed, with special machine. H. T. Ashton. *454
W. H. Booth. 605
—Cylinders, Multiple fixture for; light jig. Alley & Maclellan's. *269, *272
—Dividing-head tests, Cincinnati. *11
—Double vertical-spindle milling attachment, Kearney & Trecker. *717
—Featherways in saw collars, Attachment for milling. W. M. L. *656
—Fixture for milling auto. spring seat. H. C. Barnes. *730
—Fixture for milling Ellis adding-typewriter part. *904
—Fixture for milling tool bracket. *20
—Fixture, Milling, for slots at 90-deg. T. Dessin. *27
—Fixture on miller, Locating; motor-driven milling. N. B. Chace. *936
—Fixture, Slot-milling. B. S. Frank *29
—Fixture, Vertical-index milling, for bolt heads, etc. J. C. Hafner. *731
—Fixtures, Bracket-milling. H. C. Barnes. *672
—Gage, Cutter-setting. W. George. *102
—Gibs, Milling cast-iron. A. Erhardt. *576
—Horizontal attachment for vertical miller, Becker-Brainard. *701
—Jigs, Boring, without laying out. H. K. Krum. *321
P. S. Prince. *358
G. E. Gay, F. H. Sander. 402
O. Burt. 403
(Stops for table.) by Press. *433
(Master plates.) G. H. Bert. *588
H. P. McCabe. *623
J. G. Vincent. 796
—Keyseats, Cutting four. F. C. P. *728
—Keyway-depth table. C. W. Bennett. *179
—Milling and drilling machines, Knight, Work of. *722
—Milling job and testing fixtures; gang cutters for slotting a bar; saws, etc. L. Miller. *400
—Milling-machine knee, Automatic operation on Burk. *607
—Milling-machine, Small hand, Chicago. *183
—Milling-machine platens, Templets for. S. W. Mills. *175
—Milling-machines, Combined vertical and horizontal, Ingersoll. *918
—Milling-machines, Plain, Waltham. *186
—Milling-machines, Precision. H. P. McCabe. *623, 796
—Motor drives, Le Blond. *108
—Motor frame, Car, Machining. P. Fenaux. *384
—Nurl to be cut by miller, Laying out; finding angle of cutter. W. J. Bitterlich. *435
—Nuts, Milling hex. F. C. P. *728
—Nuts, Fixture for castellated. P. C. Halter. *136
—Oil grooves, Cutting. S. A. R. *658
—Pneumatic fixtures for double-head and straddle milling, etc. M. E. Service. *869
—Problem—Milling three chuck-jaw faces at once. J. Raquet. *176
—Quick-return motion applied to horizontal milling machine. W. G. Dunkley. *243
—Rotary milling fixture, Taft-Pierce. *972
—Screw-slotting fixture. E. Beck. *655

PAGE

—Screwdriver spirals, Milling. E. Viall. *121
—Shaper, Milling attachment for. W. L. McL. *879
—Simplex autos., Making—Thread-milling in lathe; milling cam shaft, etc. *599
—Straddle-milling a lever, Fixture for. S. W. Mills. *104
—Thread-miller work. E. Theodore. 306
—Tooth-chamfering attachment, "Long-Arm." *331
—Vise jaws, Special spring. E. J. Rantsch. *657
—Watervliet work—Backing off twist drills with conical-fluted cutter; well supported cutters; milling rapid-fire gun. *38
Misnomers, Technical. 996
Mold, Telephone-receiver cap. A. J. Jehl. *780
Molds, Monotype, Grinding, lapping, broaching, etc. *117, *77, *788
Molds, Type—Microscope. *77, *808
Molding. See also "Foundry."
Molding machines for die castings. *228
Molybdenum steels. E. F. Lake. 484, 496
Monotype making, Lanston. *77, *117, *788
Motor. See "Electricity", "Engine."
Multi-Color Copying Co.'s "Raven" system. 962
Multiplication and division, Charts for. *753

N

Nails, Case-hardening. 238
Names—Technical misnomers. 996
National Asso. of Manufacturers. 842, 219
National Mach. Tool Builders' Asso. 840, 850, 958
National Metal Trades Asso. 554, 710, 841
National Soc. for, etc., Industrial Education. 222, 256, 590, 693, 776
Natural resources, Conservation of. 665
Naval shops, Mare I. *153, *456, *568. *610, *645
Needle-threading machine. R. J. Hearne. 892
Nickel steel. E. F. Lake. *483, 511, 498, *505
Nozzle, Making special. F. E. Fick. *768
Number wheels, Veeder cyclometer, Printing; typewriter for stamping serial numbers. *797, *798
Numbering system, Gould & Eberhardt's. *374
Nurl, Laying out, to cut by miller. W. J. Bitterlich. *435
Nurling long work. E. A. Dixie. *65
Nurling on punch press. C. R. G. *581
Nurling screw threads. P. A. Fredericks. *327
Nut backs, Countersinking tool for. J. V. H. *292
T. Atherton. *324
M. E. Chase. *915
Nut-boring tools. W. T. H. *911
Nut, Howard lock. *221
Nut lock, P. C. Schmidt's. *854
Nut, Lock, that does not pull bolt end off. G. G. McV. *732
Nut, Removing Slocomb micrometer. *291, *401, 773
Nut, Sheet-metal, with nurled edges. Experimenter. *989
Nut, Split, for assembling autos. F. H. McGee. *356
Nut-tapping machine. Fay automatic. *340
Nut-tapping machine, Waterbury-Farrel. *406
Nuts, Castellated, Milling fixture for. P. C. Halter. *136
Nuts, Casting, in metal. Barnes pat. *70
Nuts, Hex, Milling. F. C. P. *728
Nuts, etc., Jigs for drilling spanner holes in. J. E. Anderson. *849. *953, *986
Nuts, Micrometer, for pendulums. *439

O

Octagon hole in gun lug. *40
Odometers, Veeder, Testing. *798
Oil and air mixer, Rotary. *154
Oil burner for shrinkage; supply tank. *241
Oil-country echoes. W. Osborne.
—A drill-press specialist. 23
—Personal factors of safety. 128
—Machining gas-engine cylinders. *194
—The foreman of No. 6. 242
—Pay for results or time? 341, 582
—Pump with peculiarities. 517
—Importance of standards. 562
—Piston rings, uniform strength. *723
—Evolution of a boring tool. *899
Oil, Fish, smell. E. Viall. 794
Oil, Fuel, for general shop-furnace use. Mare Is. navy yard. H. A. Evans. *153
Oil grooves, Cutting, on miller. S. A. R. *658
Oil-handling equipment, Kundtz' Bowser. *42
Oil hardening. E. R. Markham. *63, *619, *955
Oil engines, Novel small. A. S. Ager. *934
Oil hole and shield, Drill for. *734
Oil, Lard-, or soda water? 274, 622, 674, 914
Oil, Porpoise, for watches. 225
Oil, Rifling bearing for. W. A. M. *948
Oil separator for chips. 889
Oilstone scraper sharpener, Revolving. Mummert, Wolf & Dixon Co.'s. *544
Old machine tools, Whitney's. E. A. Dixie. *317
Operating an old game. 777

PAGE

Order system, Burroughs' Adding Mach. Co.'s. *792
Ordnance shops, Creusot works. *862
Organization, Westinghouse shop. A. Taylor. 411
Oval tapers—Derrer attachment. *148
Overload detector for cranes, Weston. *960
Oxyhydrogen, Cutting with. 320
Obermayer Bulletin †591

P

Packing, Bad, by American exporters. 776
Packing condenser tubes, Tool for. *240
Packing gland, Tool for. W. T. H. *911
Packing, Metallic, Making. W. T. H. P. A. C. King. *466 *881
Packings for high-pressure air. *633, *995
Paint, Machine, to stand heat. 971
Painting English castings and patterns. 392
Pambour on the locomotive. 334
Parabolic templets. W. Gribben. *260
Parallel lines, Pencils connected for. (Ruler.) Iron Burgh. *64 *917
Parallels for chucking. C. E. Tanner. *727
Patching hoist housing. F. H. Whitney. *137
Patent examiners, Increased pay for. 626
Patent law—Needed change; foreign rights; British law. 540, 554, 996
(Another.) Sharples Sep. Co. 624
Patent Office *Gazette*—Claims omitted. I. D. Kimball. 30 217
Patents, Natl. Asso. of Mfrs. on. 843
Pattern. See also "Foundry," "Core."
Pattern, Bevel-gear, Making. J. R. L. *618
Pattern for column. N. Patton. *431
Pattern shop, Unusual type. Maryland Steel Co.'s. H. J. Kennedy. *198
Pattern work, Plaster of paris in. 392, 771
Pattern work—Shrink-rule device. *65
Patterns, Bevel-gear tooth, Sawing. *291
Patterns for special pipe flanges. F. W. Barrows. *608
Patternmakers' gap lathe. Oliver. *606
Patternmakers' lathe. Am. W. W. M. Co.'s *147
"Patternmaking." Jas. Ritchey. †219
Pay-roll, Rapid handling of large. G. E. practice, Lynn. G. F. Stratton. *348
Pay to write? Does it; to read? 250, 252, 589, 825, 957
Paying wages. Md. Steel Co.'s. 240
Pedestal jaws, Facing loco. *552
Pencils connected for parallel lines. *64
Perpetual motion again. G. S. Echols. 815
Perpetual-motion machine. J. G. Dornbirer. 937
Pfahler, W. H., Death of. 591
Photographing without negative. *781
Piece-work experience. C. Alvord. *715
Pin shanks removed by hydraulics. W. G. H. *177
J. E. P. 355
(Another method.) H. C. *585
(Joint cup.) Rochester. *880
Pinion cutter, Automatic, Waltham. *184
Pinion shafts, Veeder cyclometer, Threading and cutting off. *797
Pipe-bending machine, Underwood. *33
Pipe-die stock, Hart. *547
Pipe fittings for high-pressure air. F. W. O'Neil. *633 *995
Pipe fittings, Metal core boxes for. *762
Pipe flanges, Patterns for special. F. W. Barrows. *608
Pipe, Gas, cut by shaft. R. C. Williams. *466
Pipe lines, Steam, Layout and installation. W. H. Miller. 232, 327
Pipe machine, Twisting iron in. G. W. Koretke. *289
Pipe, Molding 4-way stand. G. Buchanan. *312
Pipe tap, Adjustable. E. Viall. *849
Piston boring, Niles taper attachment. *413
Piston-head explosion. F. W. Collins. *892
Piston-ring blanks, Iron and castings for. A. Manchester. 684
(Machining, etc.) Y. Ziegler. 915
Piston-ring drill jig. F. E. Booth. *731
Piston-ring jig. W. J. B. *948
Piston-ring-side grinder, Saxon. *552
Piston rings, Gang tool for cutting off. M. R. Kavanagh. *988
Piston rings, Jigs for turning. W. C. Chinneck. *216
A. E. Heming. *357
Piston rings—Making Simplex autos. *603
Piston rings, Mandrel for. R. B. Allen. *585
Piston rings, Turret-lathe tool for. M. R. Kavanagh. *846
Piston rings, Uniform-strength. W. Osborne. *723
Pistons, Fixture for testing by water pressure. L. B. Allen. *378
Pistons, Machining small curved. F. J. Bostock. *346
Planer, Adjustable slot tool for. H. L. C. *691
Planer bolted down? Why is. H. E. Eberhardt, F. C. L. George, B. W. Noel. 137
H. L. Cameron, W. L. McL. 250
Entropy. 325
J. E. Sweet. 355
R. Mason. 403
D. E. D. 437
C. F. Logan. 445
(Leveling blocks.) C. A. Heald. *535
W. A. Mitchell. 535
C. H. Norton. 662
G. Langen. *670
Planer chuck and gear-planing attachment. A. E. Robinson. *941
Planer for fluting textile rolls, Woodward & Powell. *700
Planer heads, Testing. N. B. Chace. *935
Planer-hole plug, Lucas M. T. Co.'s. *978
Planer, largest in world. Mackintosh, Hemphill Co.'s Niles-Bement-Pond. F. H. C. *1
(Length of bed.) J. E. Sweet. 733
Planer, Leveling a. J. N. Heald. *931
Planer leveling blocks. G. Langen. *670
Planer, Making slotter out of. W. Alton. *618
Planer, Mandrel for keyseating on. *326
Planer-reversing devices. L. D. Burlingame. *192, *235
Planer, Rotary twin and its work—Allis-Chalmers Co.'s Bement-Miles—Floor-plate work, etc. C. Aikens. *979
Planer, 2-motor, variable-speed Niles, at LeBlond works. *825
Planer, 24-in. Rockford. *221
Planer, 36x36-inch, Notes on design of—Table, ways, bed, housings, braces, gearing, etc. Entropy. *873
Planer, 60-in. open-side Cleveland, with 52-ft. bed. *185
Planers, Fly-wheels on. J. R. Godfrey. 925
Planers, German—Ducommun. *790
Planers, Testing and using, in Landis grinder shop; use of levels. E. A. Shriver. *671
Planetary gear, Baker compound. 249
Planing castings too wide for planer by tipping. Con Wise. *728
Planing curved faces. O. B. Davies. *801
Planing multiple-punch guides—Gages for V's, Manville Bros.' *907
Planing saddle pieces to arc. E. A. Dixie. *216
W. Gribben, D. W. George. *587
S. Oliver. 773
Planing fixture, Tool-bracket. *21
Planing jig, Landis. H. F. Noyes. *325
Planing keyway in hard screw. J. Bell. *177
Planing keyways in shaper. C. L. Goodrich. *767
Planning dep't, Mare Island. *645
Plaster of paris, Shop uses of—Patterns. F. E. Fick. 392
Jas. Mack. 771
Plastic material, Dies for. G. P. Pearce. 104
Plate, Testing surface. J. H. Boulet. 438
Plugs, Taper, Turning. B. R. Asche. *955
Plugging machine, English. C. Taylor's. *392
Pneumatic. See "Air."
"Pocketbook," Sames'. †107
Pointing tool, Rod. *139, 467
Polishing lathe, Webster & Perks. *186
Polishing machine, Disk. Safety Emery Wheel Co.'s. *364
Portable German and English drills. *54
Portable-tool work on large planer. *5
Posts, Forming-tool. *303
Postal affairs, Natl. Asso. of Mfrs. on. 844
"Power and Power Transmission." E. W. Ker- †627
Power chart, Crane. A. D. Harrison. *964
Power cost, elevating material. R. Hoyt. 178
Power requirements of railroad-shop tools. L. R. Pomeroy. *91
"Power Stations," etc. G. C. Shadd. †107
Precision drilling and reaming. H. P. McCabe. *623
J. G. Vincent. 796
Precision methods, Two uses of. 328
Premium-plan experience. C. Alvord. *715
Premium system for Govt. shops. *569

PRESS.

—Ball bearings, Assembling. Chapman. *132
—Ball bearings, Tools for. Chapman. *130
—Balls, Hollow, Press tools for. O. Clerk. *442
—Conveyer hooks, Making. R. A. Gleason. *989
—Die, Blanking and drawing. T. McCabe. *687
—Die, Combined cutting and bending, for can ear. J. Sirius. *399
—Die, Follow, for magnet-head punchings for enclosed arc lamp. J. F. A. Vogt. *168
Practical. 622
—Die for corrugating copper rings for superheaters. G. A. Beaudry. *322
—Die, Forming. P. S. Huntley. *987
—Die, Hardening. E. R. Markham. *63
Jas. Steele. *619
E. Viall. *955
—Die making in large mfg. plant; standard beds; distortion of beds; holding; machining punch holders; work sub-division; guide pins and bushings. H. C. Barnes. *564
—Die, Multiple-piercing. R. J. Kruse. *950
—Die, Sectional. L. E. Salmon. *377
—Die, Sectional, Remarkable. E. Board's. *567
—Die, Shrinking a. E. A. Dixie. *467
—Die-sinking shop, Mare Island. *456
—Die, Sub-press, for punching holes in steel rings. R. A. Almond. *689
—Dies, Compound, for sheet-metal punchings—Motor laminations. K. S. Allen. *561
—Dies for Canadian coins, Making. W. L. McLaren. *530
—Dies for plastic material. G. P. Pearce. 104
—Drawing two pieces at once. W. George. *990
—Flanging press, Boiler-sheet hydraulic. Atlas Engine Works'. W. J. Withem. *682
—Foot press, Double-action tools for. E. E. Eisenwinter. *878
—Foot press with gang dies, Ferracute. *922
—Forcing press, Motor-driven, Lucas. *851
—Gang press, Automatic, Bliss. *697
—Gears, Cutting internal clutch. *602
—Gluing auto. steering-wheel rims. M. E. Grand. *617
—Guide pins, Fitting. P. F. *356
—Index die for armature punchings. K. S. Allen. *946
—Lift-out, Auto., punch press. G. K. *440
—Nurling on punch press. C. R. G. *581
—Nut, Sheet-Metal, with nurled edges. Experimenter. *989
—Press, Ferracute single-crank. *32
—Press operating two dies, Bliss. *474
—Press, Toledo large open-back. *33
—Punch and die design. Notes on—Dowels, quills, etc. C. F. Howse. *800
—Punch and die for armature segments and compound punch and die for stator segments. J. C. Haff. *910
—Punch and die holders—Master-plate work. G. H. Bert. *588
—Punch and die, Lattice-bar; holders; cracked punch. T. R. Charlton. (Hardening.) E. A. Dixie. *401 537
E. Shalaps. *881
—Punch and die, Multiple. H. R. G. *178
—Punch and split die, with automatic lever feed, for automobile cooler fronts. R. A. Almond. *174
—Punch guides, Planing multiple—V gages. *907
—Punch press, Bliss heavy. *221
—Punch-press work failures and successes. W. George. *766
—Punching die, Improved. C. Petitjean. *62
—Rakes, Making garden. J. F. A. Vogt. *84
—Register for press tools. C. Petitjean, O. D. Clerkenwell. *140
—Ring-forming tools. B. S. Frank. *767
—Solder cap hemming machine, Bliss. *778
—Spoons, Stamped, in cherry stone. *59
—Stagger-feed attachment, Bliss. *852
—Studs, Making on punch press. H. E. S. *800
—Telephone-receiver caps, Molding. *780
—Tools for small tin box. W. Sirius. *288
—Tubes, Short, Tools for. H. F. Allen *1002
—Pressed-steel auto. frames. E. J. Bartlett. *224
Pressure regulators, Air, Mare Is. *158
Prices, Machine Tool Builders and. 840, 850
Prints, Duplicating, Multi-Color Copying Co.'s "Raven" system. 962
Profile grinder, Schuchardt & Schütte's. *963
Profile steel. New Metal Co.'s Baltic. *220
(Cutter.) F. J. Bostock. *916
Profiling, Pneumatic fixtures for. *867
"Profit Making." C. U. Carpenter. †813
Projectile lathe. Firth-Sterling's Bement. *146
Projectile making, Watervliet. *37
Protractor, Draftsman's, Kelsey's. *667
Protractor, Screw adjustment. A. Hanton. *687
Pulley, Adjustable chain-belt, Whitney. *778
Pulley-balancing rig. R. Grant. *579
Pulley-crowning attachment, Mossberg. *332
Pulley—Drive vs. shrink fits. *398, 774
Pulley-turning on hand lathe. *939
Pulley—Two speeds from constant drive. *307
Pulley with nut cast in. *71
Pulleys, Balancing; testing oiling system; turning air grooves in "pneumatic" pulleys. Woods Mach. Co.'s. *337
Pulleys, Cone, Machining—Fay auto. lathe. *726
Pulleys, Cone, Turning, by Steptoe Shaper Co. G. K. Atkinson. *752
Pulleys, Grinding cone. J. H. Hollinger. *230
Pulleys of Allen drill press. *73
Pulleys, Rockford chuck for holding. *629
Pump belt—Power losses. 555
Pump, Centrifugal, impellers, Split ring for. C. W. Clifford. *322
J. B. Sperry. *811
Pump regulating valve, Foster oil. *154
Pump, Vacuum, Blake & Knowles. *1060
Pump, Weber subterranean. *69
Pump with peculiarities. W. Osborne. 517
"Pumps, Notes on." E. C. R. Marks. †31
Pumps, Bowser self-measuring oil. T. Kundtz'. *42
Punch. See also "Press."
Punch for laying out holes. J. A. Early. *292

Q

Questions for shop men, etc. J. R. Godfrey. 274, 622, 914

PAGE

Quick-return devices, etc. L. D. Burlingame. *189, *234
Quick-return motion applied to horizontal miller. W. G. Dunkley. *243

R

Rack cutter, Auto., Gould & Eberhardt. *545
Rack cutting with hob. Cheney patents. *573
Rack, Sliding, for dwell of table. *237
Racks, Tool. Woods Machine Co.'s. *336
Racks, Toolroom. W. H. Taylor. *122
Rails, Underground, Method of laying. 267

RAILROAD.

—Locomotive frame, Straightening. D. R. Llewellyn. *719
—Locomotive, Pambour on the. 334
—Loco.-pedestal jaws, Facing—Underwood machine. *552
—Loco. shop, Creusot works. *860
—Loco.-frame drill, 4-spindle, Harrington, for Am. Loco. Wks. *886
—Loco. side frames, Vanadium-steel. *532
—Loco. tools and fixtures—Machining rocker arms; grinding ball reamers; cat heads for hub work; drill-press tools, tube-hole cutter, etc. L. E. Saimon. *86, *461
—Loco.-wheel lathe, Heavy, Sellers. *864
—Loco. work, Niles boring mill. *413
—"Railway Shop Up to Date." †107
—Tools, Power for. L. R. Pomeroy. *91
Rakes, Tools for making garden. J. F. A. Vogt. *84
Rapieff flange joint. *640, *995
Read? Does it pay to. A. L. Pratt, A. R. Allan et al. 252, 274, 589, 825, 957, 985
Reamer, Expanding, for blind hole. G. Buswell. *398
Reamer, Expanding rose. C. Taylor's. *391
Reamer holder, Floating. A. Sanderson. *802
Reamer, Hollow, for Skinner engine wrist pins. E. A. Dixie. *395
Reamer, Turney high-speed adjustable. *592
Reamer, 3-piece roughing, keyhole. E. Viall. *353
Reamer wrench. Noumac. *580
Reamers for choke-boring shot-gun barrels. E. N. Amory. *614
Reamers for locomotive work; ball-reamer grinding fixture. *86
Reamers for metal core boxes. *763
Reamers, Measuring with scale. Entropy. 325
Reaming bench, Compressed-air, Chicago. *686
Reaming bench with balance. Noumac. *580
Reaming Cadillac cylinders. *114
Reaming, Precision. H. P. McCabe. *623, 796
Reaming valve body accurately, Tool for. M. R. Kavanagh. *360
Recessing machine, Renold chain-stud. *16
Recessing tool for long work in turret lathe. J. P. Essex. *103
John E. Sweet. *733
Recessing tool. J. Herbert. *58
Recessing tool. S. E. L. *801
Recessing tools, Nut. *292, *324, *915
Reciprocity, Natl. Asso. of Mfrs. on. 219, 843
Record performances. J. R. Godfrey. 925
"Red-hardness," Steel. E. F. Lake. *483
Reel bracket. B. C. Hay. *803
Refrigerating apparatus, German. 41
Regeneration of the old shop. *335
Register for press tools. C. Petitjean, O. D. Clerkenwell. *140
Removing broken pins. *177, *355, 585, *880
Renold, Hans, Ltd., works, J. W. Carrel. *416
Repair parts, High charges for. J. Smith. 149
Reports, Shop. H. A. Evans. *610, *645
Rest and follow, Schellenbach lathe. *832
Rest, Compound—Thread cutting. *58, *62, 396, 139, *293, 325, 387, 396, 534, 578, 588, 663, 880, 916
Rest, Steady, for crank-shafts. *835
Rests, Box-tool. Goodrich & Stanley. *207, 468
Rests, Lathe, Roller. G. H. Handley. *988
Results or time? Pay for. 341, 582
Reversal, Friction-clutch, Walker grinder. *145
Reversing mechanisms. L. D. Burlingame. *189, *234
Reynolds, Geo. H., Death of. 106
Rheostats, Westinghouse d.-c. starting. *475
Rifling bearing for oil. W. A. M. *948
Rifling mandrel, Making, E. C. Peck. *429
Rifling 10-inch gun slope. *40
Rigidity tests of dividing head. *14
Ring-forming tools, Simple. B. S. Frank. *767
Ring, Split, for centrifugal-pump impellers. C. W. Clifford. *322
J. B. Sperry. *811
Rings, Copper, for superheaters, Die for corrugating. G. A. Beaudry. *322
Rings, Iron, Making with limited tools. E. O. J. *691
Rings, Steel, Sub-press die for punching holes in. R. A. Almond. *689
Rivet-heating furnace. E. Balbach. *262
Riveter, Boiler, installations, Albree. *56
Rocker arms, Machining locomotive. *86
Rockland tidal air-compressing plant. *44
Rod ends, Gage for. J. S. Scott. 727

PAGE

Rod ends, Standard, Billings & Spencer. 923
Rod-pointing tool. C. C. Mason. *139, 467
Roll-fluting planer, Woodward & Powell. *700
Roll turning at Kneeland shops. *893
Rolls, Making textile. G. A. Dexter. *26
Roller bearings. See "Bearings."
Roller rest, Box tool with. *209
Rolling machine, Barrel-bead, Toledo. *448
Rolling-mill drive, Elec. Ill. Steel Co.'s. *51
Rolling-mill engine, 25,000-h.p. *745
Rolling, Spiral, of metal. O. Clerkenwell. *617
Rolling steel. E. F. Lake. *510
Rolling threads on edges of disks. *798
Roof, Lucas M. T. Co.'s. *977
Roof, Saw-tooth, variation. Md. Steel Co.'s. *198
"Roof Trusses." N. C. Ricker. †363
Rotary twin planers, Allis shop. *979
Roughing-out machines, Stops for. *444
Rounding ends of gear teeth. J. F. Wells. *580
Rubber, Dies for hard. G. P. Pearce. 104
Rubber—Ebonite-recessing tool. J. Herbert. *58
Rubber—Molding telephone-receiver caps. *780
Rubber tools, Hardening. G. Harfmann. 881
Rubber, Turning—Grinding. H. A. Richmond. 623
Rubber washer cutter. E. Viall. *213
Rubber, Working. A. N. Hammond. 752
Ruler for parallels. Iron Burgh. *917

S

Saddle pieces, etc., to arc, Planing. *216, *587, 773, *801
Safety device, Drop-hammer. R. Grimshaw. *102
Safety device in chain driving. *18
Safety Devices, Museum of. 298, 630, 891
Sales, Form for conditional; collections. 90
Sand-blast machine as electrical generator. B. O'Reilly. 172
Sand-blasting machine, Leiman Bros.' *741
Saw, Cold, Burk Machy. Co.'s. *851
Saw, Hack, Draw-cut, Armstrong-Blum. *922
Saw, Hack, Revolving, Eclipse. *999
Saw, Hack, Tandem. Buffalo Specialty Co.'s. *924
Saws, Cold, English high-speed; pneumatic feed. Roberts Bros'. J. W. Chubb. *984
Saws, Grinding milling. E. Viall. *462
J. O. Surface. 773
Sawing bevel-gear teeth, Attachment for. A. E. Owen. *291
Sawing machine, English hack. F. C. Perkins. *668
Scale, Counting and weighing, National *817
Scale measurements, Accurate. W. S. Romell. 239
(Measuring reamers.) Entropy. 324
Scale with decimal equivalents. A. E. C. 690
Scales of circle diameter and area. *753
School. See "Education."
Scleroscope, The. *508, 223, 350, *675
Scraper, Oilstone, sharpener, Mummert, Wolf & Dixon. *544
Scraping bearing surfaces. H. L. Cameron. 249
D. C. Howard. 291
Scraping fixture, Motor-driven. N. B. Chace. *937
Scraping in building Lucas boring mill. *976
Scraping taper gage. N. B. Chace. *935

SCREW.

—See also "Tap," "Worm."
—Bushings, Screw, and jigs. *101, *175, *287, 443, *471, *735
—Die chasers, Hobbing. Dixie. *653
—Die stock. Pipe, Hart. *547
—Ends, Finishing. R. D. Morse. *732
—Keyway in hard screw, Planing. J. Bell. *177
—Lead of screws, Machine for measuring. Hendey and Cincinnati M. M. companies'. *685
—Machine screws, Standard, Use of. 66
—Plate, Screw, for brass tubing, Wiley & Russell. *367
—Screw-cutting attachment for 13-in. English lathe—Turret, chuck, etc. B. E. Church. *100
—Screw-driving machines, Reynolds. *677, 960
—Screw-machine cams, Cleveland machine for milling. J. P. Brophy. *902
—Screw machine—Circular forming-cutter problem; cutting-off tools. *443, *810, *880
—Screw machine, Cleveland, Cam adjusting. *275
—Screw-machine countersinking tool for nut backs. *292, *324, *915
—Screw machine, Cross-drilling attachment for National-Acme. J. Acton. *628
—Screw machine, Improvements in Spencer 5-spindle automatic. *703
—Screw machine, Motor-driven, Cleveland. *855
—Screw machine, Preparing stock. C. C. Mason, P. W. Abbott. *139, *467

PAGE

—Screw machine, Acme auto., Tapping attachment for. A. Klein. *927
—Screw-machine turning and forming tools, Automatic. Goodrich & Stanley. *207, *299
McK. 468, *775
—Screw-machine work, Cleveland auto. —Time required. F. H. Colvin. *526, *422
—Screw machines, Automatic, Dies and taps for. Goodrich and Stanley. *379
—Screw machine, Spencer automatic, Epicyclic train of. H. S. *799
—Screw machines, Hollow mills for. *622
—Screw machines, Motor drive for, Nat'l Acme. *884
—Screw making in Chile. A. Prince. 817
—Screws, Accurate, Making in lathe. Theodore. *952
—Screws, Clamp for holding. F. P. *214
—Screwdriver spirals, Milling, E. Viall. *121
—Silver bone screws, Making. G. Sands. *581
—Slotter, Screw, Auto., Taylor & Fenn. *704
—Slotter, Screw, Simonds. *331
—Slotting machine, Screw, Waterbury-Farrel. *333
—Slotting fixture, Miller. E. Beck. *655
—Thread-cutting job; driving lathe from lead screw. H. Egloff. *615
—Thread cutting, Niles boring mill. *412
—Thread cutting on English lathes. 734
—Thread-miller work. E. Theodore. 306
—Thread milling in lathe; threading in drill press—Making Simplex auto. *599
—Thread tools, Measuring. H. F. Atkins *71
—Threads, Cutting V; compound rest. (Tool for one side.) E. J. Bowers. *58
(Various tools.) J. Watson. *62
C. A. Marston. 396
C. H. Wells. 139
John E. Sweet. *293, 387, 578
Entropy. 325
J. T. Slocomb. 534
(Circular chaser.) M. A. Young. 588
(Spiral-fluted taps.) E. Viall. 660
C. H. Erb. 663
John E. Sweet. *773
C. G. Kranz. 880
P. W. Abbott, F. F. Pease. 916
—Threads, Nurling screw. P. A. Fredericks. *327
—Threads, Standard. W. Osborne. 562
—Threads, Stock size for bolts with rolled. S. A. Gorman. 177
—Threading auger leaders. *282
—Threading by rack feed on Morris Fdy. Co.'s lathe. *826, *831
—Threading lathe, Fay automatic. *339
—Threading on lathe, Rapid. E. S. Williams. *467
—Threading tool, Combined boring and. P. A. Frederick. *175
—Threading tool. F. E. Ross'. *816
—Threading Veeder cyclometer pinion shaft; rolling threads on edge of disks. *797
—Wood screws, Measurement of round-head. Am. Screw Co.; Corbin Screw Corp. 91, 193
Scriber, Toolmakers'. G. F. MacNavy. *214
Secret, Keeping—Skewer pointing machine. 837
Sector for dividing between holes. M. H. Ball. *103
Selecting machine equipment. J. R. Godfrey. 345, 623
Sellers, Dr. Coleman, Death of. *67
Separator, Steam-driven, for cleaning chips. Oil & Waste Saving Machine Co.'s. *889
Shaft. See also "Crank-shaft."
Shaft coupling, Oval. *148
Shaft cut into by gas pipe. *466
Shaft, Flexible, Coates. *885
Shaft-hanger box. Olney & Warrin's. *738
Shaft hangers, Clamping, at Lucas shop. *978
Shaft suspension, Line. Md. Steel Co.'s. *202
Shaft-twisting moment — Alinement chart. *760
Shafts, Aliining, by steel wire. A. H. Nourse. *338, 770
Shafts, Gas-engine. W. H. Booth. 575
Shafts, Sizes of, without mathematics —Chart. J. H. Barr. *900
Shafting, Straightening. D. W. James. *847
Shaper, Cincinnati, Mill's bevel-gear planing attachment for. *642
Shaper, Cross-feed attachment, Gould & Eberhardt. *366
Shaper, Cutting internal gears on. F. H. C. *574
Shaper fixture—Gun sights. J. J. Seibert. *141
W. Cantelo. *621
Shaper, Milling attachment for. W. L. McL. *879
Shaper, Planing keyways in. C. L. Goodrich. *767
Shaper, Queen City—New geared drive. *737
Shaper shop, Cincinnati, methods and tools—Testing vises, columns, etc. N. B. Chace. *935
Shaper tool post, Suggested. T. A. Sparks. *215

PAGE

Sheet metal. See "Bending," "Press," "Joint," "Core boxes," "Nut."
Shims, Trays for. F. Oyen. *98, 360
Ship's sternpost, Repairing—Thermit weld. *388
Shipbuilding on Tyne. J. W. Carrel. 351
Shop, Clearing up old. B. H. Spencer. 367
Shop education, Progressive. F. A. Waldron. 522
Shop equipment in dull times. 295
Shop, Job, vicissitudes. J. G. Dornbirer. 525, 667, 742, 747, 793, 837, 863, 937
Shop, Job, experience. Y. Ziegler. 992
Shop, Lucas M. T. Co.'s. *974
Shop, Machine, methods. H. A. Evans. —Analysis—Government-shop inefficiency; labor affairs; foremen's pay; "day work"; time losses; toolroom methods; equipment; speeds, etc. *568
—General instructions—Damage and other reports; records of material and labor; foremen's meetings, etc. *610
—Detail instructions, planning dep't. cards, orders, etc. *645
Shop of Hans Renold, Ltd. *416
Shop organization, Westinghouse. A. Taylor. 411
Shop, Regeneration of old— S. A. Woods. Mach. Co.'s. *335
Shop, School. See "Education."
Shop, The old and new. Noumac. *580
Shop training for engineers. Entropy. 248, 806
Shop work in Chile. A. Prince. 817, 908
Shops, Creusot. J. B. Van Brussel. *857
Shops. Maryland Steel Co.'s. *198, *240
Shrink-rule device. W. Gribben. *65
Shrinkage heats, Kerosene burner for. *241
Shrinkage. See "Hardening," "Wood."
Shrinking a die. E. A. Dixie. *467
Sights, Gun, Shaper fixtures for. *141, *621
Simplex automobiles, Making. *599
Size-block box. G. B. Howe. 403
L. F. Charles. *914
Size blocks, Standard, Bullard. *713
Sizing tool for lathe. A. Pedro. *360
Skewer-pointing machines—Keeping secret. 837
Slide-rule accuracy. 64, 469
Slides, Measuring dovetail. F. H. Scheu. *650
Slot-milling fixture. B. S. Frank. *29
Slotter, Dill right-angle drive. *34
Slotter extended to keyseat hubs. *241
Slotter head, large Bement planer. *6
Slotter out of planer, Making. W. Alton. *618
Slotter, Screw, Auto., Taylor & Fenn. *704
Slotter, Simonds screw. *331
Slotting attachment, Small hole. G. Bilham. *460
Slotting-bar tool box. O. B. Davies. *727
Slotting gun lugs. *40
Slotting machine, Hand-driven portable. Engels & Waegner's. *961
Slotting machine, Screw, Waterbury-Farrel. *333
Slotting-machine tool bar with frictionless return. J. Green. *26
Slotting, Screw, miller fixture. E. Beck. *655
Smoke-Abatement Report, Syracuse. †363
Smoke, Coal burning without. 142
Sockets, Reducing—Standard drill shanks. *296, 774, 993
Soda water or lard oil. 274, 622, 674, 914
Solder cap hemming machine, Bliss. *778
Solder cutter for jewelers, Bliss. *740
Solder for aluminum. 781
Soldering process—"Tinol." 749
South Africa, American trade in. 93
Spanner holes—Drill jigs. J. E. Anderson. *849, *953, *986
Sparrow's Point works. H. J. Kennedy. *240, *198
Speed box, Radial-drill, Gang Co.'s. *854
Speed-changing device—Gear box. E. S. P. *586
Speed control, Cutting-off machine. Hurlburt-Rogers. *553
Speed counter, Vest pocket, American. *999
Speed indicator. Veeder Mfg. Co.'s. *529
Speed—Reversing devices. L. D. Burlingame. *189, *234
Speed, Securing any cutting, on Morris Fdy. Co.'s Schellenbach lathe. *829
Speed, Variable, transmission device. Dieterich—Floating-disk principle. F. H. C. *838
Speeds Cutting, Govt. shop. *572
Speeds, Cutting, of new steels—Fischer's report. R. Grimshaw. 217
Speeds, Steel-cutting. E. F. Lake. 516
Speeds, Two, from constant-speed drive. A. Walton. *307
Spherical seats, Boring bar for. A. Newman. *658
Spindle, Adjustable drill. C. A. Edwards. *324
Spindle-boring lathe, LeBlond double-ended. *707
Spindle-boring machine, Oesterlein. *743
Spindle, Dividing-head, tests. *12
Spindle, Drill—Transverse hole, etc. *58, 620, *621
Spindle—Drive vs. shrink fits. *398, 774

PAGE

Spindles, Machine, Standardizing. F. Oyen. *296, 774, 993
Spiral rolling of metal. O. Clerkenwell. *617
Spirals, Instrument for generating. L. W. Charles. *809
Spirals, Milling screwdriver. E. Viall. *121
Spoons in cherry stone. *59
Spring breakage, Preventing. Entropy. E. Viall. *955
Spring seat, Auto., milling fixture. H. C. Barnes. *730
Spring tempering; diagram. E. F. Lake. *497
Spring-testing fixture. A. C. H. *396
Springs, Cutting coiled. F. W. Fullerton. *358
Springs, Making tapered. W. L. McLaren. *799
Springs, Safety-valve, Machine for grinding. Hammett Co.'s. *465
Springs, Square, Tests of. O. James. *578
Springs, Using helical. A. Jackson. 368
Square hole, Expanding. E. A. Dixie. *845
Square, Machine-shop. J. E. Sweet. *929
Square taper hole, Making. 764
Squares, Bullard device for testing. *714
Squares, Knife-edge. Lanston Co.'s. *120
Stagger-feed attachment, Press, Bliss. *852
Stamping job, Fine. G. P. Swain. *59
Stamping numbers, Typewriter for. *798
Stand-pipe, Molding 4-way. G. Buchanan. *312
Stand, Tool, Bullard. *714
Standard rod and yoke ends. 923
Standards, Drafting. Gould & Eberhardt's. *372
Standards, Importance of. W. Osborne. 562
Standardizing spindles and arbors. F. Oyen. *296, 774, 993
Stator-core segment punch and die. *910
Stay-bolt cutter, Landis. *146
Steady rest for crank-shafts. *835
Steam-pipe lines, Layout and installation. W. H. Miller. 232, 327
Steam-Properties Tables. C. H. Peabody. †473, †813
"Steam Traps, Modern." G. Stuart. †31
Steel. See also "Hardening," "Limit," etc.
Steel alloy, Nickel—"Invar." 613
Steel alterations in heat treating. J. E. Storey et al. *277, *359, 442, *463, 735
See also "Iron."
Steel and its uses—Furnaces and mfg. processes; electric furnaces; ingredients and materials; alloys; heat treatment, annealing, hardening, tempering, carbonizing; furnaces; microscopic examinations; properties; wearing qualities; testing; rolling, forging, welding, casting, machining, and effects. E. F. Lake. *477
Steel, Case-hardening with gas, etc.—American gas furnace. E. F. Lake. *263, *497
Steel castings, Vanadium in; Union Steel Castings Co.'s practice. E. F. Lake. *532
Steel for hardness, Testing. E. R. Markham. 223
(Standard hardness.) W. H. Fleet. 350
E. F. Lake. *507
(Electromag. tester.) E. F. Lake. *557
Steel, Hardening, restoring, etc. J. Steele. 673
Steel, Hardness in. A. F. Shore. *675
Steel, High-speed, cutters—Durability. 872
Steel, High-speed, formed milling cutters. *453, *605
Steel, High-speed, Treating. E. R. Markham. 134
E. S. Wheeler. 660
Steel, High-speed, Treatment of, various brands. E. Viall. 314
(D. S. W. steel.) R. Langlin. 808
Steel, Machine, V-blocks flake off? Why do. M. R. Kavanagh. 65
Steel-mill machinery, Machine work on —Kneeland shops. E. F. L. *893
Steel, Pressed, auto. frames. E. J. Bartlett. *224
Steel, Profile. New Metal Co.'s Baltic. (Milling cutter.) F. J. Bostock. *916
Steel, Structural, tests, Watertown. 30
Steel used in boilers: J. H. Heck on ship plates. W. H. Booth. 408
Steel, Weights of bar. W. Sangster. 587
C. E. Parsons. 916
Steel works, Creusot. J. B. Van Brussel. *857
Steels, New, Cutting speeds. 217
Steels—Technical misnomers. 996
Sternpost, Repairing—Thermit weld. *388
Still used to reclaim gasolene. *891
Stock-in-progress and finished stock, Handling of. A. J. Doughty. *792
Stool, All-metal. Mfg. Equip. Co.'s. *222
Stop, Friction, for micrometers, Slocomb. *924
Stop-pin shanks by hydraulics, Removal of. W. G. H. et al. *177, 355, *585, *880
Stops for miller table. Cy. Press. *433
Stops, Positive, for machines. F. W. B. *444

PAGE

Stopping—Reversing mechanism. *235
Straddle-milling fixture. S. W. Mills. *104
Straightening hardened tools. T. Foot. 649
Straightening locomotive frame. D. R. Llewellyn. *719
Straightening machine, Rockford. *366
Straightening shafting. D. W. James. *847
"Strength of Materials." W. C. Popplewell. †591
Structural designer, Triangle for. *64
Stud-drilling jig. P. W. Abbott. *393
Stud-recessing machine, Renold. *16
Studs, Making on punch press. H. E. S. *800
Sub-drill, Multi-spindle. F. H. Stead. *414
Success as test of reliability. 218
Sulphur as lubricant. A. N. Hammond. 213
E. A. Dixie. 441
H. L. Butler. 733
Superintendent, Legal knowledge for. O. E. Perrigo. 41, 620
Surface-plate work—Crank-shafts. *834
Surfacing broach for Bullard wrench. *463
Swindling game New. Victim. 139
System, Use your, or kill it. 812

T

T-slot cutters. *22
T-slot sizing tool. Lucas M. T. Co.'s. *978
Tally board, English toolroom. *252
Tangs on twist drills. F. Oyen. *296
R. Brown. 774
A. H. Matson, A. Frederic. 993
Tank for hardening small pieces. *57
Tank, suppiy, for kerosene burner. *242
Tanks, Oil-storage, Kundtz'. *43
Tap and die holder. G. Harfmann. *881
Tap, Pipe, Adjustable. E. Viall. *849
(Tap continued after "Taper.")
Taper attachment, New Haven lathe. *183
Taper attachment, Schellenbach lathe. *831
Taper attachment. W. L. McLaren. *799
Taper attachment, Niles boring mills. *413
Taper gage, Accurate. C. C. Stutz. *458
Taper gage, Scraping and testing. *935
Taper-hole tests, Dividing-head. *11
Taper plugs, Turning. *392, *955
Taper-turning attachment, Zange. *183
Taper-turning box tool. *209
Taper work, Saving time in. C. H. W. *327
Tapers, Wax, for cores. J. B. Sperry. 849
Taps, Backing off, with grinder. *38
Taps, Broken, Using — Rockford method. *945
Taps distorted in hardening. A. Gwaikokujin. *359
Taps for auto. screw machines. Goodrich and Stanley. *379
Taps, Removing broken. J. Sutherland. 140
J. Schuring. 286
Taps, Rolled, Remington. E. A. Dixie. 102
I. B. Rich. 216
Taps, Spiral-fluted. E. Viall. 660
C. H. Erb. 663
J. E. Sweet. 387, *773
P. W. Abbott. 916
Taps, etc., Extensions on. 735
Tapping attachment for Acme automatic. A. Klein. *927
Tapping, boring, etc., machine, Baker. *698
Tapping collars in lathe. G. Allen. *443
Tapping device, Hand, for rails. P. W. Abbott. *803
Tapping device. W. M. *731
Tapping fuse bushings. *37
Tapping machine, Home-made. A. J. Baker. *761
Tapping machine, Nut, Fay automatic. *340
Tapping machine, Nut, Waterbury-Farrel. *406
Tapping to shoulder with automatic tap. O. Johnson. *934
Tariff, Natl. Asso. of Mfrs. and. 219, 843
Technical graduate. See "Education."
Teeth. See "Gearing," "Cutter."
Telephone-receiver cap mold. A. J. Jehl. *780
Tell-tales for machines. F. W. B. *444
Temperatures, Annealing—Howe's laws. 491
Temperatures by different scales. 753
Tempering. See also "Hardening."
Tempering steel. E. F. Lake. *496
Templet, Blackened zinc—Master cams. *308, 584
Templets for milling-machine platens. S. W. Mills. *175
Templets, Laying out parabolic and elliptic. W. Gribben. *260
Test. See also "Indicator," "Level," etc.
Tests, Chapman double ball-bearing. *129
Tests, Cincinnati dividing-head. *11
Testing and setting tool. Dynamic. *912
Testing cyclometers and odometers. *798
Testing Lucas boring mill. *976
Testing shaper and planer parts, turret lathe, taper gage and gear cutter. N. B. Chace. *935
Testing squares, Bullard device for. *714
Testing steel. E. F. Lake. *504
Testing steel for hardness. 223, 350, *507, *557
Thermit welds. *240, *388, 516

PAGE

Thread. See "Screw," "Tap," "Worm."
Tidal air compressing. W. O. Webber. *44
Tie bars, Air fixtures for milling. *871
Time or results? Pay for. W. Osborne. 341
W. Longstreet, G. H. Handley. 582
Time recorder for machine tools. Card's at Lodge & Shipley shop. N. D. Chard. *595
H. A. Dudgeon. 954
Entropy. 994
Time required for machine work—F. H. Colvin—Norton grinding examples. *422
Cleveland screw machine. *526
Time shortening on contract job. F. E. Brown. *709
"Tinol." 749
Titanium, Ferro-. 919
Titanium in steel. E. F. Lake. 485
Tobin-bronze for art work. 233

TOOL.

—See also "Machine tool," "Cutter," "Press," "Steel," "Hardening," etc.
—Angles, Tools for laying out. W. T. Dillaway. *292
—Bar, Slotter-tool. J. Green. *26
—Beat tool for clock escapements. W. Gribben. *439
—Boring and threading tool, Combined. P. A. Frederick. *175
—Boring-mill tools and accessories, Bullard—Cutting tools; O. K. combination holder; tool stand, etc. *713
—Boring tool, Adjustable, for turret lathe. W. Alton. *581
—Boring tool, Evolution of. W. Osborne. *899
—Boring tool, Expanding. J. Wheeler. *438
—Boring tool for turret lathe, Adjustable. J. E. Ritchie. *213
—Boring tool, Readily removable. H. H. G. *949
—Boring-tool holder, Mayer's. *553
—Conveyer, Tool. P. G. Roberts. *24
—Core-box work, Special tools for metal. Viall and Voelcker. *762
—Counterboring and facing tool. M. R. Kavanagh. *913
—Countersinking screw machine tool for nut backs; use of deflector, etc. J. V. H. *292
T. Atherton. *324
M. E. Chase. *915
—Cut? Why does a drill. 405, 581, 625
—Cutting-off tool for old guns. W. de Sanno. *104
—Cutting-off tools for screw machines. *880, *443, *810
—Cylinders, Auto; Bardons & Oliver tools for machining. *531
—Cylinders, Alley & Maclellan's auto. —Tools for valve sheet. *273
—Designer's trouble. A. J. Baker. 253
W. C. Hartly. 285
—Dust cap, Machining. B. J. Williams. *971
—English tools—C. Taylor's—Revolving lathe center; gages; reamer. *391
—Expanding or undercutting tool for drill press. C. B. Kirkham. *529
—Facing-tool angles. R. D. Morse. *732
—Facing tool, Double. W. R. G. *360
—Forming-tool holder slide for round work. J. Braum's. R. Grimshaw. *991
—Forming tools, Circular. J. C. Richardson. *845
—Grinding, Injuring tools in. J. S. Dyson. 774
—Hand turning tools. J. Lomas. *939
—Handles, Bluing. F. Webster. 985
—Hardening rubber tools with cyanide. 881
—Head of large Bement planer. *3
—Holder for bar tools. C. H. *659
—Holder, Tool, Clamp bushings for—Turning and facing fixtures. E. I. Phipps. *440
—Holder, Tool, Combination; keyseating, Western Tool & Mfg. Co.'s. *258
—Holder, Tool, Combination, Meadowcroft's. 407
—Holder, Tool, Improved. A. E. Clark. *327
—Holders, Tool, Multiple, for eccentric turning. E. A. Johnson. *688
—Holders, Turret-tool. Hammett Co.'s. *465
—Improvised tools for new shop—Holder that deepens heavy cut, etc. Noumac. *580
—Lathe, Sellers wheel—Tool turrets. *865
—Loco. tools and fixtures—Machining rocker arms; reamers and cutters; fixture for grinding; cat heads for hub work; drill-press tools, tube-hole cutter, etc. L. E. Salmon. *86, *461
—Monotype inspection, Tools for. *120
—Packing, Making metallic. *466, *881
—Piston rings, Gong tool for cutting off. M. R. Kavanagh. *988
—Piston rings, Turret-lathe tool for. M. R. Kavanagh. *846
—Post, Shaper tool. T. A. Sparks. *215
—Posts, Tool, Standard. F. Oyen. *98
O. T. Watt. 360
—Profile-steel tools. *220, *916

PAGE

—Recessing tool for long work in turret lathe. J. P. Essex. *103
John E. Sweet. *733
—Recessing tool for ebonite. J. Herbert. *58
—Recessing tool. S. E. L. *801
—Rod-pointing tool. C. C. Mason. *139, 467
—Rolls, Tools for wooden. *26
—Screw-machine forming tools, Making circular and dovetail—Clearances, finding diameters, transfer scheme, master tools and templets, dovetail tools, tool posts, supporting long work, making short screws and other parts. Goodrich and Stanley. *299
(Side clearance, circular tools.) McK. *775
—Screw-machine turning tools, Automatic—Box tools, cutters, rests, hollow mills and clamp collars, taper-turning tools, etc. Goodrich and Stanley. *207
McK. 468
—Shaper-shop tools, Cincinnati. *935
—Shop tools, Bench-lathe. F. J. LeCard. *244
—Sizing tool for lathe. A. Pedro. *360
—Slot tool, Adjustable, for planer. H. L. C. *691
—Slotting bar tool box. O. B. Davies. *727
—Speeds, Cutting, of new steels—Fischer's report. R. Grimshaw. 217
—Straightening hardened tools. T. Foot. 649
—T-slot sizing tool, Lucas Co.'s. *978
—Testing and setting tool. Dynamic. *912
—Thread-cutting, V—One side only. E. J. Bowers. *58
(Various tools.) J. Watson. *62
C. A. Marston. 396
C. H. Wells. 139
John E. Sweet. *293, 387, 578
Entropy. 325
J. T. Slocomb. 534
(Circular chaser.) M. A. Young. 588
(Spiral-fluted taps.) E. Viall. 660
C. H. Erb. 663
John E. Sweet. *773
C. G. Kranz. 880
P. W. Abbott, F. F. Pease. 916
—Threading tool. F. E. Ross'. *816
—"Tool Making." E. R. Markham. †219
—Toolmaking in large mfg. plant—Gang divisions, drawings, records, etc.; milling and lathe work; die and jig making. H. C. Barnes. *564
—Toolmaking, School of—Wanted. 294
—Toolmaking without drawings. S. Taylor. 749
A. Frederic. 919
L. P. Sittig. 957
—Toolroom arrangement and system. W. H. Taylor. *122
—Toolroom methods, Govt. H. A. Evans. *568, *610, *645
—Toolroom system, Alley & Maclellan's. *268
—Toolroom system, English. R. Charlton. *252
—Toolroom system; racks. Woods Mach. Co.'s. *335
—Tools and drives—Making Simplex autos. *603
—Turning tool, Machining turret-lathe. Alfred Herbert Ltd.'s. A. J. Baker. *20
—Turret lathe, Gridley multi-spindle. *164
—Turret-lathe tool for sizing shoulders. E. C. O. *361
—Turret-lathe tools, Special—Nut-boring; box tool; gang tool for valve cap; making packing gland. W. T. H. *911
—Turret tool holder, Lathe, Bocorselski's. *906
—Undercutting tool for Prentice turret machine. R. Grant. *293
(Tools of wider adaptability.) Prentice & Co. *772
—V-tool measurement; table for angles. H. F. Atkins. *71
Tooth. See "Gearing," "Cutter."
Torsion tests, Steel. E. F. Lake. *506
Tracing drawings—Details. W. J. Chipman. 245
Tracing-paper drawings; tracing blueprints. *203
Tracings, Straightening. D. T. Fletcher. 580
T. Andrews. 663
P. W. Abbott, S. R. Newton, J. F. Storz, J. Peterson, G. M. Diehl. *770
Trade, Machine Tool Builders and. 840, 850
Trade—Machinery export, etc. 161, 179, 423, 719, 780, 862, 995
Trade, Natl. Asso. of Mfrs. on. 842
Trade school. See "Education," "Apprentice."
Training. See "Education."
Transfer scheme—Circular forming tools. *301
Transmission, Variable-speed, Dieterich. *838
Trays for shims. F. Oyen. *98
Triangle for drawing beam flanges. *64
Triangle, Graduated. A. H. Stork. *727
Truck for Lucas boring machine. *976
Truck, Railway auto., Westinghouse. *70
Truing ways of Bement planer. *8
Tube-hole cutter, Loco. boiler. *88

PAGE

Tubes, Short, Press tools for. H. F. Allen. *1002
Tubing, Chart for collapsing pressure of. *759
Tubing, Screw-plate for brass, Wiley & Russell. *367
Tungsten steels. E. F. Lake. 483, 496
Turbine bucket, Milling a. *701
Turbine casings, Boring bars for. T. M. Lowthian. *464
Turbine cupola blowers, Sturtevant. *541
Turbines, etc., Balancing. *8, *579
Turning. See "Lathe," "Tool," "Screw," (sub-entry "Screw machine"), "Piston," "Rubber," etc.
Turret attachment for sensitive drill. R. Brown. *60
Turret-drilling attachment for drill press or lathe. Patterson Tool & Supply Co.'s. *960
Turret for cartridge cases, Bardons & Oliver. *945
Turret for screw-cutting attachment. *100
Turret-head, Duplex, boring mill, Richards. *391
Turret lathe. See "Lathe," "Screw machine," (under "Screw"), etc.
Turret tool holder for lathe, Bocorselski's. *906
Twisting iron in pipe machine. G. W. Koretke. *289
Twisting moment, Shaft—Alinement chart. *760
Twisting rake teeth, Machine for. *85
Type. See "Molds."
Typewriter for stamping numbers. *798

U

Undercutting tool for turret machine. R. Grant. *293
G. G. Prentice & Co. *772
United Eng. Co.'s Kneeland plant. *893
Universal shape attachment, Derrer. *147

V

V's, Measuring. F. H. Scheu. *650
V-center for drilling, Lathe. *661, 954
V-block with sliding center. A. H. Stock. *727
V-blocks of machine steel flake off? Why do. M. R. Kavanagh. 65
V-tool measurement. H. F. Atkins. *71
Vacuum pump, Blake & Knowles. *1000
Value of manufacturing property. 404
Valve, Blower-relief, Mare Is. *158
Valve body, Tool for accurately reaming. M. R. Kavanagh. *360
Valve bodies, Hexing. E. Viall. *604
Valve cap, Gang tool for. W. T. H. *911
Valve chamber, Machining Cadillac. *115
Valve, Foster oil-pump regulating. *154
Valve jobs—Different methods. S. Laurence. *654
Valve, Molding 3-way reciprocating. W. W. McCarter. *18
Valve-seat recutting tool. *323
Valve seats, Casting faces on. W. H. Bewers. *621
Valve sheet, Special tools for auto. cylinder. Alley & Maclellan's. *273
Valves for high-pressure air. *633, *995
Valves, Metal core boxes for. *762
Vanadium in cast iron. R. Moldenke. 297
Vanadium in steel castings; Union Steel Castings Co.'s practice. E. F. Lake. *532
Vanadium steels. E. F. Lake. 485, 511, 498, *505, 511, 514
Variable speed. See "Speed," "Planer," "Gearing," etc.
Veeder cyclometer, Making the. F. H. C. *797
Vernier caliper and depth gage, German. New Metal Tool Steel Co.'s. *259
Vernier for boring-bar adjustment. *434
Vernier, Hole locating with. G. E. Gay. 402
Venier, Indexing 5-min. H. K. Harring. *214
Verniers, Work with. H. P. McCabe. *623
J. G. Vincent. 796
Vertical-spindle attachment, Double, Kearney & Trecker. *717
Vibrational testing of steel. *509
Vise defect. G. H. Wood. *214
Vise jaws, Special spring. E. J. Rantsch. *657
Vise-testing fixture. N. B. Chace. *935
Vision, Acute, in shop measurements. *808

W

Wabble drills. *24, *733, *734
Wages, Paying. See "Pay."
Warsaw, Permanent exposition in. 1002
Washer broach, Adjustable. E. Viall. 691
Washer cutter, Rubber. E. Viall. *213
Washer, Special tool-post. *98, 360
Washers, Fiber friction. H. A. Burt. 415
(Brake shoe.) Gagnier. 879
Waste-cleaning machine. *890
Watches, Oil for lubricating. 225
Water jacket, Spun-copper. *114
Water-level gage, Bristol recording. *258
Watertown arsenal's steel tests. 30
Watervliet, Interesting work. *37
Wax tapers for cores. J. B. Sperry. 849

PAGE

Weighing machine, Counting and, National. *817
Weights of bar steel. 587, 916
Welds, Thermit. *240, *388
Welding, Autogenous, Applications. W. I. Reich. *316
Welding chain. H. Barnes. *949
Welding, Oil-fire, Mare Is. *159
Welding steel, etc. E. F. Lake. *514
Westinghouse shop organization. A. Taylor. 411
Wheel, Car, boring mill, Sellers. *741
Wheel, Car, chill, Carr's new. *425
Wheel, Loco., lathe, Heavy, Sellers. *864
Wheel, Molding mower. A. D. Mundy. *537
Wheel rims, Press for gluing auto. steering. M. E. Grand. *617
Wheel journals, Turning—Belt tire drive. H. W. Jacobs. 418
Wheels, Car, Boring and facing. B. W. T. *394
Wheels, Number, Veeder cyclometer. *797
Wheels, Split, Locking connecting links in rims. B. Brownstein. *445
Whitney's, B. D., antique tools. *317
Wind, Electric power from, Denmark. 79
Windmill experiments, Danish. 722
Winona technical institute. 294, 328, 554, 711
Wire-drawing dies—McFarland foundry. *718
Wire sags in alining shaft bearings, Table of; wire reel. M. Preston. *338 770
Wires, Threading and cutting off—Making Veeder cyclometer. *797
Wood-pulp plant, Starting a. 863
Wood shrinkage lengthwise. E. T. Strong. *463
Wooden rolls, Making. G. A. Dexter. *26
Woods, S. A., Machine Co.'s shop. *335
Worcester Polytechnic, Tool design. *932
Work benches, Four styles of. *352
Worm-gear drive, New arrangement of. T. A. Weston. 140
Worm gears, Making small. E. C. O. *216
Worm-wheel hobber, Auto. Eberhardt Bros.' *998
Worm-wheel hobber, Cincinnati. *10
Worm wheels, Index, LeBlond hobber for. W. F. Groene. *897
Worms, Steep-pitch, Cutting on engine lathe. W. L. K. *579
Wrench, Bullard, Surfacing broach for. *463
Wrench, Drill-chuck key. B. M. Weller. *729
Wrench, Cheap reamer. Noumac. *580
Wrench dies, Simple. T. Toot. *847
Wrench, Monkey, Use in emergency. E. A. Charles. *61
Wrist pin, Gas-engine. Pinning. *323
Wrist pins, Hollow reamer for. *395
Write? Does it pay to, etc. E. R. Markham, T. D. West et al. 250, 252, 589

Y

Yoke ends, Standard, Billings & Spencer. 923